

Infrastructure Description	Forest Preserve	Amenity Condition	Maintenance Needs	Remaining Life Span (Estimate)	Inspection Notes
Pond aerator	Baker Woods F.P.	Poor	Replacement	0-5	Dosent work
Drain tile outlet	Baker Woods F.P.	Poor	Replacement	0-5	
Derelict building	Baker Woods F.P.	Poor	Removal	0-5	
Sign	Baker Woods F.P.	Poor	Replacement	0-5	Needs a new sign
Parking	Baker Woods F.P.	Fair	Structural Repairs	6-10	Needs gravel
Ellis house	Baker Woods F.P.	Fair	Structural Repairs	6-10	Needs new roof, needs paint, some windows need to be replaced, some floors need refinishing
Dry lot enclosure	Baker Woods F.P.	Fair	Structural Repairs	6-10	
Main barn/arena	Baker Woods F.P.	Fair	Structural Repairs	6-10	Needs new roof
Bridge	Baker Woods F.P.	Fair	Structural Repairs	6-10	
Bridge	Baker Woods F.P.	Fair	Structural Repairs	6-10	Needs erosion control
Interpervtive sign	Baker Woods F.P.	Fair	Structural Repairs	6-10	Sign is showing wear
East loop	Baker Woods F.P.	Fair	Structural Repairs	6-10	Needs to regraded
Bridge	Baker Woods F.P.	Fair	Structural Repairs	6-10	Some boards need replaicing, need debri cleared
Shelter	Baker Woods F.P.	Good	Cosmetic	11-15	Needs paint
Shelter	Baker Woods F.P.	Good	Cosmetic	11-15	Needs paint, damaged tables
Information	Baker Woods F.P.	Good	Cosmetic	11-15	Needs paint and new cork board
south loop	Baker Woods F.P.	Good	Cosmetic	11-15	
Parking	Baker Woods F.P.	Good	Cosmetic	11-15	
Information	Baker Woods F.P.	Good	Cosmetic	11-15	
Parking	Baker Woods F.P.	Good	Cosmetic	11-15	Needs to be restriped
Storage unit	Baker Woods F.P.	Good	Cosmetic	11-15	
Trail	Baker Woods F.P.	Good	Cosmetic	11-15	
Storage barn	Baker Woods F.P.	Good	Cosmetic	11-15	
Well pump	Baker Woods F.P.	Good	Cosmetic	11-15	
Restrooms	Baker Woods F.P.	Good	Cosmetic	11-15	Needs paint
Culvert	Baker Woods F.P.	Good	Cosmetic	11-15	
Culvert	Baker Woods F.P.	Good	Cosmetic	11-15	
Culvert	Baker Woods F.P.	Good	Cosmetic	11-15	

Gate	Baker Woods F.P.	Good	Cosmetic	11-15	Needs paint
Drain tile	Baker Woods F.P.	Good	Cosmetic	11-15	
Sign	Baker Woods F.P.	Good	Cosmetic	11-15	Lights dont work
Culvert	Baker Woods F.P.	Good	Cosmetic	11-15	
Tent pad	Baker Woods F.P.	Excellent	None	16-20	
Propaine tank	Baker Woods F.P.	Excellent	None	16-20	
Sign	Baker Woods F.P.	Excellent	None	16-20	
Sign	Baker Woods F.P.	Excellent	None	16-20	
Interpertive sign	Baker Woods F.P.	Excellent	None	16-20	
Map	Baker Woods F.P.	Excellent	None	16-20	
Map	Baker Woods F.P.	Excellent	None	16-20	
Bench	Baker Woods F.P.	Excellent	None	16-20	
Map	Baker Woods F.P.	Excellent	None	16-20	
Storm drain man hole	Baker Woods F.P.	Excellent	None	16-20	
Seasonal Restroom	Baker Woods F.P.				
Fishing	Baker Woods F.P.				

Parking	Blackberry Creek F.P.	Poor	Replacement	0-5	
Interpertive sign	Blackberry Creek F.P.	Poor	Replacement	0-5	Missing sign
Interpertive sign	Blackberry Creek F.P.	Poor	Replacement	0-5	Sign is missing
Interpretive sign	Blackberry Creek F.P.	Poor	Replacement	0-5	Missing sign
Interpretive sign	Blackberry Creek F.P.	Poor	Replacement	0-5	Sign is nissing
Wooden fence	Blackberry Creek F.P.	Poor	Replacement	0-5	Fence is falling apart and a tree has fallen on one end
Trail section	Blackberry Creek F.P.	Fair	Structural Repairs	6-10	Tree roots have pushed up parts of this trail
Trail section	Blackberry Creek F.P.	Fair	Structural Repairs	6-10	Erosion where bicycles have been going off the trail threatens to weaken the paved trail. Some gravel should help
Foot bridge	Blackberry Creek F.P.	Fair	Structural Repairs	6-10	A few boards starting to rot. A bit of graffiti
Trail section	Blackberry Creek F.P.	Good	Cosmetic	11-15	
Trail section	Blackberry Creek F.P.	Good	Cosmetic	11-15	Parts of trail degraded. No immediate repairs needed, but should be inspected again next spring at the latest
Garbage/doggie bags	Blackberry Creek F.P.	Good	Cosmetic	11-15	Can lid needs to be replaced
Garbage/doggie bags	Blackberry Creek F.P.	Excellent	None	16-20	
Sign	Blackberry Creek F.P.	Excellent	None	16-20	
Retaining wall	Blackberry Creek F.P.	Excellent	None	16-20	
Culvert	Blackberry Creek F.P.	Excellent	None	16-20	

Foot bridge	Harris F.P.	Poor	Repair	0-5	Downed tree on top, railings need repair, leaf litter and soil need to be cleaned away
Culvert pipe	Harris F.P.	Poor	Replacement	0-5	Cant find the other end
Culvert	Harris F.P.	Poor	Replacement	0-5	Washed out
Fence	Harris F.P.	Poor	Replacement	0-5	
Fence	Harris F.P.	Poor	Replacement	0-5	
Cement silo	Harris F.P.	Poor	Removal	0-5	Full of stagnant water
Fountain	Harris F.P.	Poor	Replacement	0-5	Fountain needs replaicing spigot is ok
Building	Harris F.P.	Fair	Structural Repairs	6-10	Some missing siding, needs paint
Sled Hill	Harris F.P.	Fair	Structural Repairs	6-10	Need some filler up top where the sleds have dug ruts, gravel in stairs.
Parking	Harris F.P.	Fair	Structural Repairs	6-10	Broken post by entrance, need to install culvert at entrance
Water	Harris F.P.	Fair	Structural Repairs	6-10	No valve handle
Asphalt trail	Harris F.P.	Fair	Structural Repairs	6-10	Need patched by back pond and guardrail, asphalt crumbling in places
Shelter 7	Harris F.P.	Fair	Structural Repairs	6-10	Needs paint, corners of foundation cracking, cement needs moss and lichen removed, support bolts need to be cut off
Foot bridge	Harris F.P.	Fair	Structural Repairs	6-10	Need to clear the leaf litter now and then it is decomposing on the planks of the bridge, needs erosion control
Foot bridge	Harris F.P.	Fair	Structural Repairs	6-10	Needs to be leveled and needs erosion control
Foot bridge	Harris F.P.	Fair	Structural Repairs	6-10	Needs erosion control
Old outhouse	Harris F.P.	Fair	Structural Repairs	6-10	Big hole in roof
Lake drain	Harris F.P.	Fair	Structural Repairs	6-10	Clogged
Culvert	Harris F.P.	Fair	Structural Repairs	6-10	Need gravel to cover
Fire ring	Harris F.P.	Fair	Structural Repairs	6-10	Need more stones, benches need work
Baseball diamond	Harris F.P.	Fair	Structural Repairs	6-10	Need resurfacing
Flag pole	Harris F.P.	Fair	Structural Repairs	6-10	Not used, needs a rope and flag

Shelter 4	Harris F.P.	Fair	Structural Repairs	6-10	Lights inside need cleaning, needs paint, back door needs replaicing, windows need repair or replaicment, chimney needs cleaning, front door needs replaicingclean furnace enclosure
shelter 3	Harris F.P.	Good	Cosmetic	11-15	Outlet covers needed, paint job, bolts need to be flush cut
Parking	Harris F.P.	Good	Cosmetic	11-15	Could use sealcoat
Restroom	Harris F.P.	Good	Cosmetic	11-15	Needs a paint job
Shelter 2	Harris F.P.	Good	Cosmetic	11-15	Paint, cut bolts, power outlet covers
Parking	Harris F.P.	Good	Cosmetic	11-15	Small cracks starting nothing bad, could use fresh sealcoat
Building	Harris F.P.	Good	Cosmetic	11-15	Paint
Shelter 6	Harris F.P.	Good	Cosmetic	11-15	Needs paint, recycling bin, outlet covers
Restroom	Harris F.P.	Good	Cosmetic	11-15	Needs a paint job
Horse Arena	Harris F.P.	Good	Cosmetic	11-15	Fence posts heaving, picnic tables need new planks and or paint, arena needs to be leveled out water is pooling
Information	Harris F.P.	Good	Cosmetic	11-15	A little rust, needs paint
Water	Harris F.P.	Good	Cosmetic	11-15	
Picnic area	Harris F.P.	Good	Cosmetic	11-15	Need new garbage can lid and a proper base for the can to sit on
turn around	Harris F.P.	Excellent	None	16-20	
Parking	Harris F.P.	Excellent	None	16-20	Asphalt cracking due to tree roots pushing up
Gate	Harris F.P.	Good	Cosmetic	11-15	Paint
Gate	Harris F.P.	Good	Cosmetic	11-15	Paint
Gate	Harris F.P.	Good	Cosmetic	11-15	Paint
Foot bridge	Harris F.P.	Good	Cosmetic	11-15	Needs leaves cleared
Foot bridge	Harris F.P.	Good	Cosmetic	11-15	Needs leaves cleared
Foot bridge	Harris F.P.	Good	Cosmetic	11-15	Needs a little gravel at either end
Foot bridge	Harris F.P.	Good	Cosmetic	11-15	Needs to have leaves cleared. One railing board needs to be replaced.
Well	Harris F.P.	Good	Cosmetic	11-15	
Foot bridge	Harris F.P.	Good	Cosmetic	11-15	

Shelter 1	Harris F.P.	Good	Cosmetic	11-15	Trim needs work
Sign	Harris F.P.	Excellent	None	16-20	
Culvert	Harris F.P.	Excellent	None	16-20	
	Harris F.P.				
	Harris F.P.				
	Harris F.P.				
	Harris F.P.				
	Harris F.P.				
Shelter 1	Harris F.P.				
Water	Harris F.P.				
Shelter 3	Harris F.P.				
Shelter 7	Harris F.P.				
Shelter 4	Harris F.P.				
Observation Area	Harris F.P.				

Campground	Hoover F.P.	Poor	Site clearing, tree removal	0-5	Very over grown needs lots of clearing most sites unusable
Indian Village	Hoover F.P.	Poor	Replacement	0-5	Shelters need to be rebuilt
Wind turbine	Hoover F.P.	Poor	Replacement or removal	0-5	Dosent work
Old cabin	Hoover F.P.	Poor	Demolition	0-5	
Old cabin	Hoover F.P.	Poor	Demolition	0-5	
Old shop	Hoover F.P.	Poor	Heavy repairs, new doors, new roof, siding, fence	0-5	
old water tank	Hoover F.P.	Poor	Removal	0-5	
Hoover well pump house	Hoover F.P.	Poor	Replace roof, insulation and weather stripping,	0-5	We are currently shocking the well with bleach every 6 months, the smell continues to return
Pool	Hoover F.P.	Poor	Demolition	0-5	Needs to be demolished
Culvert	Hoover F.P.	Poor	Replacement	0-5	Clogged and buried
Old outhouse	Hoover F.P.	Poor	Removal	0-5	
Old outhouse	Hoover F.P.	Poor	Removal	0-5	
Old outhouse	Hoover F.P.	Poor	Removal	0-5	
Old outhouse	Hoover F.P.	Poor	Removal	0-5	
Pump house	Hoover F.P.	Poor	Replacement	0-5	Currently inoperable
Culvert	Hoover F.P.	Poor	Replacement	0-5	Too small, clogs frequently, cant handle high flow events, causes flooding and washes away road.
Blazingstar Cabin	Hoover F.P.	Fair	Structural Repairs	6-10	Paint job, carpenter bee damage, wood pecker damage, window frame in bunkroom needs to be fixed, crawlspace needs insulation and sealing off, back door weatherstrip ceiling needs work, kitchen needs tile work under sink,
Moonseed Cabin	Hoover F.P.	Fair	Structural Repairs	6-10	Carpenter bee damage around door and window frames, needs paint, need nww chairs, missing tiles in kitchen under sink, need new stove, need scaffolding to patch drywall on ceiling,

Kingfisher Cabin	Hoover F.P.	Fair	Structural Repairs	6-10	Weather stripping, replace chairs, missing tiles, exhaust fan replaicment, missing tiles, crawlspace ventilation, exit door jammed, oven needs replaicing, paint job, carpenter bees, foundation needs sealing
Eagle's Nest	Hoover F.P.	Fair	Structural Repairs	6-10	Needs paint, shakes falling off front and back, loose shingles, bent mounting hardware at base of 2 pillars, need erosion contol around foundation and sidewalk, trim needs repair, needs new tables, power outlet cover missing
Shelter	Hoover F.P.	Fair	Structural Repairs	6-10	Needs new roof, bent mounting hardware at base of 1 support, needs new trim, needs new tables, shakes falling off front and back
Kendall County Outdoor Educa	Hoover F.P.	Fair	Structural Repairs	6-10	New shingles, leaky spigot, new rear door and frame, front awning needs to be properly anchored, bathroom needs ventilation, new trim around roof, replace shed,
Front sign	Hoover F.P.	Fair	Structural Repairs	6-10	A little mortar around the stones, graffiti removal, solar panels and lights do not work properlyk
Blazingstar pavilion	Hoover F.P.	Fair	Structural Repairs	6-10	Cracked masonry, rotten support beams
Blazingstar primitive cabins	Hoover F.P.	Fair	Structural Repairs	6-10	Rotten pillers, rodent damage, damaged woodwork
Moonseed primitive cabins	Hoover F.P.	Fair	Structural Repairs	6-10	Bunks need replaicing, lots of rodent damage, damage to woodwork, front support post rotting
Moonseed pavilion	Hoover F.P.	Fair	Structural Repairs	6-10	Rotten support beams, cracked masonry
Bridge	Hoover F.P.	Fair	Structural Repairs	6-10	Some planks need replaicing, needs paint
B-box?	Hoover F.P.	Fair	Structural Repairs	6-10	Half buried
Electrical eagles nest/hobbit tu	Hoover F.P.	Fair	Structural Repairs	6-10	Loose ground connection
B-box	Hoover F.P.	Fair	Structural Repairs	6-10	Key is bent
Manhole	Hoover F.P.	Fair	Needs inspection	6-10	
Lagoon fence	Hoover F.P.	Fair	Structural Repairs	6-10	Gate needs repair

Lagoons	Hoover F.P.	Fair	Structural Repairs	6-10	
Manhole	Hoover F.P.	Fair	Structural Repairs	6-10	Need to talk to Jay
Meadowhawk lodge	Hoover F.P.	Good	Cosmetic	11-15	Weather stripping on doors, gutters repaid, fire place conversion, patio bricks scaling,
Restroom	Hoover F.P.	Good	Cosmetic	11-15	Needs paint job, mens roon sign needs replaicing
Parking	Hoover F.P.	Good	Cosmetic	11-15	Solar panels and lights do not work
Shop	Hoover F.P.	Good	Cosmetic	11-15	Weather stripping, general maintenance
Sign	Hoover F.P.	Good	Cosmetic	11-15	Needs paint
Railroad underpass	Hoover F.P.	Good	Cosmetic	11-15	
Fuel tanks	Hoover F.P.	Good	Cosmetic	11-15	
Front parking lot	Hoover F.P.	Good	Cosmetic	11-15	Herbicide spray, regrading
Front gate	Hoover F.P.	Good	Cosmetic	11-15	Chain needs to be more visable
Sign	Hoover F.P.	Good	Cosmetic	11-15	Could use paint
Bench	Hoover F.P.	Good	Cosmetic	11-15	
Bridge	Hoover F.P.	Good	Cosmetic	11-15	
River overlook	Hoover F.P.	Good	Cosmetic	11-15	
Amphiteatre	Hoover F.P.	Good	Cosmetic	11-15	Needs weed control
River overlook	Hoover F.P.	Good	Cosmetic	11-15	
Bench	Hoover F.P.	Good	Cosmetic	11-15	
Transformer box	Hoover F.P.	Good	Cosmetic	11-15	Overgrown
Transformer box	Hoover F.P.	Good	Cosmetic	11-15	
B-box	Hoover F.P.	Good	Cosmetic	11-15	
Manhole sewer access	Hoover F.P.	Good	Cosmetic	11-15	Need to secure
Transformer box	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	Need to secure but have access
Hydrant	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
B-box	Hoover F.P.	Good	Cosmetic	11-15	
Sewer cleanout	Hoover F.P.	Good	Cosmetic	11-15	
Sewer cleanout	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	

Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Sewer cleanout	Hoover F.P.	Good	Cosmetic	11-15	
B-box lodge	Hoover F.P.	Good	Cosmetic	11-15	
Hydrant and b-box	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Hydrant	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Transformer box	Hoover F.P.	Good	Cosmetic	11-15	
Electrical box	Hoover F.P.	Good	Cosmetic	11-15	
Lift station	Hoover F.P.	Good	Cosmetic	11-15	
Foot bridge	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Manhole	Hoover F.P.	Good	Cosmetic	11-15	
Man hole and 2 stand pipes	Hoover F.P.	Good	Cosmetic	11-15	
Man hole	Hoover F.P.	Good	Cosmetic	11-15	
Man hole	Hoover F.P.	Good	Cosmetic	11-15	
Panel box	Hoover F.P.	Good	Cosmetic	11-15	
Sign/hitching post	Hoover F.P.	Excellent	None	16-20	
Information	Hoover F.P.	Excellent	None	16-20	
Sewer cleanout	Hoover F.P.	Excellent	None	16-20	
Sewer cleanout	Hoover F.P.	Excellent	None	16-20	
Sewer cleanout	Hoover F.P.	Excellent	None	16-20	
Sewer cleanout	Hoover F.P.	Excellent	None	16-20	
Water fountain	Hoover F.P.	Excellent	None	16-20	
Transformer box	Hoover F.P.	Excellent	None	16-20	
Sewer cleanout	Hoover F.P.	Excellent	None	16-20	
Sewer cleanout	Hoover F.P.	Excellent	None	16-20	
Transformer box	Hoover F.P.	Excellent	None	16-20	
Transformer box	Hoover F.P.	Excellent	None	16-20	

Sewer cleanout	Hoover F.P.	Excellent	None	16-20	
Stand pipe	Hoover F.P.	Excellent	None	16-20	
The Rookery	Hoover F.P.				
Parking	Hoover F.P.				
Parking	Hoover F.P.				
Parking	Hoover F.P.				
Camp Site B	Hoover F.P.				
Camp Site A	Hoover F.P.				
Camp Site C	Hoover F.P.				
Observation Area	Hoover F.P.				
Sled Hill	Hoover F.P.				
Camp Site	Hoover F.P.				
Ranger Residence	Hoover F.P.				
Hoover Fox River Overlook	Hoover F.P.				
Hoover Fire Ring	Hoover F.P.				
Baseball Diamond	Hoover F.P.				

Water	Jay Woods F.P.	Poor	Replacement	0-5	Heavily damaged
Turf trail	Jay Woods F.P.	Fair	Structural Repairs	6-10	Drainage pipes exposed due to erosion, trailhead near shelter needs mulch
Crushed limestone trail	Jay Woods F.P.	Fair	Structural Repairs	6-10	Muddy patches needs more limestone, drainage pipes filling with mud
Culvert	Jay Woods F.P.	Fair	Structural Repairs	6-10	Mostly filled in
Parking	Jay Woods F.P.	Good	Cosmetic	11-15	Potholes
Parking	Jay Woods F.P.	Good	Cosmetic	11-15	Some potholes developing
Restroom	Jay Woods F.P.	Good	Cosmetic	11-15	Needs a paint job
Shelter	Jay Woods F.P.	Good	Cosmetic	11-15	Broken power outlet cover
Building corn crib	Jay Woods F.P.	Good	Cosmetic	11-15	Needs a paint job, damage to the bottom of the doors, cracked floor
Observation Area	Jay Woods F.P.	Good	Cosmetic	11-15	A few bumpers on the ramp are a little loose
Information	Jay Woods F.P.	Excellent	None	16-20	
Information	Jay Woods F.P.	Excellent	None	16-20	
Horse trail	Jay Woods F.P.	Good	Cosmetic	11-15	Needs more limestone to level out settling over culvert
Gate	Jay Woods F.P.	Good	Cosmetic	11-15	Paint
Gate	Jay Woods F.P.	Good	Cosmetic	11-15	Needs paint
Interperative sign	Jay Woods F.P.	Good	Cosmetic	11-15	A little water damage at the edges, one small hole on face of sign
Interperative sign	Jay Woods F.P.	Good	Cosmetic	11-15	A little water damage around the sides
Interperative sign	Jay Woods F.P.	Good	Cosmetic	11-15	A little water damage aroundn the edges
Handicap accessible trail ramp	Jay Woods F.P.	Good	Cosmetic	11-15	Boards are weathered but still solid
Drainage pipe	Jay Woods F.P.	Good	Cosmetic	11-15	One grate appears to be clogged
Bench	Jay Woods F.P.	Excellent	None	16-20	
Culvert	Jay Woods F.P.	Excellent	None	16-20	
Culvert	Jay Woods F.P.	Excellent	None	16-20	
Culvert	Jay Woods F.P.	Excellent	None	16-20	
Bench	Jay Woods F.P.	Excellent	None	16-20	
Bench	Jay Woods F.P.	Excellent	None	16-20	
Bench	Jay Woods F.P.	Excellent	None	16-20	
Sign	Jay Woods F.P.	Excellent	None	16-20	

Paved walkway with stone ben	Jay Woods F.P.	Excellent	None	16-20	No damage, might want to add gravel or mulch around the edges for erosion control
Fire ring	Jay Woods F.P.	Excellent	None	16-20	
Culvert	Jay Woods F.P.	Excellent	None	16-20	
Culvert	Jay Woods F.P.	Excellent	None	16-20	
	Jay Woods F.P.				

Outhouse	Little Rock Creek F.P.	Poor	Removal	0-5	
Outhouse	Little Rock Creek F.P.	Poor	Removal	0-5	
Outhouse	Little Rock Creek F.P.	Poor	Removal	0-5	
Outhouse	Little Rock Creek F.P.	Poor	Removal	0-5	
Spigot	Little Rock Creek F.P.	Poor	Removal	0-5	
Outhouse	Little Rock Creek F.P.	Poor	Removal	0-5	
Spigot	Little Rock Creek F.P.	Poor	Removal	0-5	
Outhouse	Little Rock Creek F.P.	Poor	Removal	0-5	
Dam	Little Rock Creek F.P.	Poor	Removal	0-5	
Culvert	Little Rock Creek F.P.	Poor	Replacement	0-5	Needs a grate on one end, culvert pipe needs repair in multiple spots
Old barn	Little Rock Creek F.P.	Poor	Removal	0-5	
Stairs	Little Rock Creek F.P.	Poor	Replacement	0-5	
Well head and vault	Little Rock Creek F.P.	Poor	Replacement	0-5	
Bridge	Little Rock Creek F.P.	Fair	Structural Repairs	6-10	Needs planking and guard rails
Retaining wall	Little Rock Creek F.P.	Fair	Structural Repairs	6-10	Needs a guard rail
Culvert	Little Rock Creek F.P.	Fair	Structural Repairs	6-10	Need a lot of erosion control at both ends, guard rail to short and incomplete
Culvert	Little Rock Creek F.P.	Fair	Structural Repairs	6-10	Needs a grate on one end, other end needs erosion control
Gate	Little Rock Creek F.P.	Good	Cosmetic	11-15	
Parking	Little Rock Creek F.P.	Excellent	None	16-20	
Information	Little Rock Creek F.P.	Excellent	None	16-20	
Foot bridge	Little Rock Creek F.P.	Excellent	None	16-20	Yet to be finished
Turf trail to overlook	Maramech F.P.	Poor	Repair	0-5	Trail is washed out in one location and threatened by erosion in at least two more locations.
Interpretive signs	Maramech F.P.	Poor	Replacement	0-5	
Observation Area	Maramech F.P.	Fair	Structural Repairs	6-10	A few supports are starting to rot. Conservation area signs need replacing
Bridge	Maramech F.P.	Fair	Structural Repairs	6-10	Need some erosion control
Parking	Maramech F.P.	Good	Cosmetic	11-15	
Information	Maramech F.P.	Good	Cosmetic	11-15	

Restroom	Maramech F.P.	Good	Cosmetic	11-15	
Water	Maramech F.P.	Good	Cosmetic	11-15	Needs a cap on top to prevent tampering
Shelter	Maramech F.P.	Good	Cosmetic	11-15	Could use some paint, some shingles look loose
Bench 1	Maramech F.P.	Good	Cosmetic	11-15	Front plank on seat is cracked
Bench	Maramech F.P.	Good	Cosmetic	11-15	front plank on seat is cracked
Interpretive sign	Maramech F.P.	Good	Cosmetic	11-15	Pictures difficult to see need to replace plexiglass
Grill	Maramech F.P.	Good	Cosmetic	11-15	A little rust and flaking paint
Gate	Maramech F.P.	Good	Cosmetic	11-15	
Crushed limestone trail	Maramech F.P.	Good	Cosmetic	11-15	Need some gravel near the fork
Sign	Maramech F.P.	Excellent	None	16-20	

Parking	Millbrook South				
Silo	Millbrook North F.P.	Poor	Removal	0-5	
Metal shack	Millbrook South F.P.	Poor	Removal	0-5	
Metal shack	Millbrook South F.P.	Poor	Removal	0-5	
Old shelter	Millbrook South F.P.	Poor	Removal	0-5	Falling apart
Barn	Millbrook South F.P.	Poor	Removal	0-5	
Shed	Millbrook South F.P.	Poor	Removal	0-5	
Corn crib	Millbrook South F.P.	Poor	Removal	0-5	
Barn	Millbrook North F.P.	Fair	Structural Repairs	6-10	
Silos	Millbrook South F.P.	Good	Cosmetic	11-15	
Parking	Millbrook South F.P.	Good	Cosmetic	11-15	
Parking	Millbrook South F.P.	Good	Cosmetic	11-15	
Parking	Millbrook North F.P.	Excellent	None	16-20	
Parking	Millbrook North F.P.	Excellent	None	16-20	

Electrical pole	Pickerill-Pigott F.P.	Poor	Replacement	0-5	Pole is rotting
Street lamp	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	Needs electricity
Street lamp	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	Needs electricity
Electrical pole	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	Needs new light fixture
Barn	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	Servicable but needs some work
Old well	Pickerill-Pigott F.P.	Fair	Assesment	6-10	
Electrical pole	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	Holes up top
Electrical pole	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	Holes near the top
Gate	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	
Electrical pole	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	Leaning
Pickerill house floor drain outlet	Pickerill-Pigott F.P.	Fair	Structural Repairs	6-10	
Culvert	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Buried cable	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Barn	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Culvert	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Culvert	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Electrical pole	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Electrical pole	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Electrical pole	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Electrical pole	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Electrical pole	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Electrical pole	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Electrical pole	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Electrical pole	Pickerill-Pigott F.P.	Good	Cosmetic	11-15	
Transformer	Pickerill-Pigott F.P.	Excellent	None	16-20	
Electrical pole	Pickerill-Pigott F.P.	Excellent	None	16-20	
Electrical pole	Pickerill-Pigott F.P.	Excellent	None	16-20	
Gate	Pickerill-Pigott F.P.	Excellent	None	16-20	

Sign	Lyon F.P.	Fair	Structural Repairs	6-10	One post is cracked
Boardwalk	Lyon F.P.	Fair	Structural Repairs	6-10	Needs to be leveled out and possibly extended at the southern end, some supports are rotting
Parking	Lyon F.P.	Good	Cosmetic	11-15	Needs new gravel
Bench	Lyon F.P.	Good	Cosmetic	11-15	Some cosmetic damage, paint job
Gate	Lyon F.P.	Excellent	None	16-20	
Observation Area	Richard Young F.P.	Poor	Replacement	0-5	Missing sections of guard rail, lots of graffiti
Foot bridge	Richard Young F.P.	Poor	Replacement or relpair	0-5	Creekbed washed out under one support twisting the bridge, some planks beginning to rot
Directional sign	Richard Young F.P.	Poor	Replacement	0-5	Missing part of the sign
Interpertive sign	Richard Young F.P.	Poor	Replacement	0-5	Sign is missing
Foot trail entrance	Richard Young F.P.	Poor	Signage, possibly a gate	0-5	This trail leads off onto private property and is not well marked, the signs that are here need repair or replacement
Foot bridge	Richard Young F.P.	Poor	Replacement	0-5	Going to wash away soon
Interpretive sign	Richard Young F.P.	Poor	Replacement	0-5	Looks terrible
Grills	Richard Young F.P.	Poor	Replacement	0-5	One of two grills is missing, grill is rusty could use paint
Grills	Richard Young F.P.	Poor	Replacement	0-5	One of two grills is missing, grill is rusty could use paint
Sign	Richard Young F.P.	Poor	Repair	0-5	Both posts are badly cracked
Shelter	Richard Young F.P.	Fair	Structural Repairs	6-10	Carpenter bee infestation, needs paint, shingles may need to be replaced, reservation sign needs to be replaced
Parking	Richard Young F.P.	Fair	Structural Repairs	6-10	Crushed parking block, faded signs, large potholes
Shelter	Richard Young F.P.	Fair	Structural Repairs	6-10	Needs new shingles, needs paint
Observation Area Hepatica hill	Richard Young F.P.	Fair	Structural Repairs	6-10	Lots of graffiti, stairs beggining to rot bench needs paint, top stair on north side is loose
Bench	Richard Young F.P.	Fair	Structural Repairs	6-10	Needs gravel to prevent further erosion, could use some paint
Directional sign	Richard Young F.P.	Fair	Structural Repairs	6-10	Signs are old and faded wood is dryrotting

Foot bridge	Richard Young F.P.	Fair	Structural Repairs	6-10	Beams on the sides are loose starting to rot
Wooden stairs	Richard Young F.P.	Fair	Repair	6-10	Stairs are starting to rot out
Paved walkway	Richard Young F.P.	Fair	Structural Repairs	6-10	Erosion has cleared the soil out from under the pavement
Restroom	Richard Young F.P.	Good	Cosmetic	11-15	Needs a paintjob
Information	Richard Young F.P.	Good	Cosmetic	11-15	Tackboard inside needs repair
Directional sign	Richard Young F.P.	Good	Cosmetic	11-15	Old and beat up but this one is still solid
Small boardwalk	Richard Young F.P.	Good	Cosmetic	11-15	
Interpertive sign	Richard Young F.P.	Good	Cosmetic	11-15	Needs paint
Interpertive sign	Richard Young F.P.	Good	Cosmetic	11-15	Could use some paint
Paved walkways	Richard Young F.P.	Good	Cosmetic	11-15	Parts of the walkway are buried under sediment
Gate	Richard Young F.P.	Good	Cosmetic	11-15	Just needs paint
Foot bridge	Richard Young F.P.	Excellent	None	16-20	
Foot bridge	Richard Young F.P.	Excellent	None	16-20	
Fire ring	Richard Young F.P.	Excellent	None	16-20	
Water	Richard Young F.P.				

Rules and regulations sign/stat	Shuh Shuh Gah Canoe La	Poor	Replacement	0-5	Needs to be replaced
Chain gate	Shuh Shuh Gah Canoe La	Poor	Replacement	0-5	Only one post
Sign	Shuh Shuh Gah Canoe La	Poor	Replacement	0-5	Currently missing
Wooden fence	Shuh Shuh Gah Canoe La	Poor	Replacement	0-5	Needs to be replaced or removed
River bridge	Shuh Shuh Gah Canoe La	Poor	Renoval	0-5	Bridge supports crumbling, some boards starting to rot
Culvert	Shuh Shuh Gah Canoe La	Fair	Structural Repairs	6-10	This culvert is nearly filled with sediment
Gate 2	Shuh Shuh Gah Canoe La	Fair	Structural Repairs	6-10	Stone pillar needs to be pushed back into place and repaired, the gate is bent but functional, needs paint
Parking	Shuh Shuh Gah Canoe La	Fair	Structural Repairs	6-10	Should have a guard rail on the river side
Parking	Shuh Shuh Gah Canoe La	Good	Cosmetic	11-15	Developing potholes
Canoe Launch	Shuh Shuh Gah Canoe La	Good	Cosmetic	11-15	Needs to be cleaned up it is half buried under mud, some of the large stones need to be moved back into placr
Shelter	Shuh Shuh Gah Canoe La	Good	Cosmetic	11-15	Needs a paint job, needs trees trimmed back around the roof
Culvert	Shuh Shuh Gah Canoe La	Good	Cosmetic	11-15	Starting to fill in a little
Culvert	Shuh Shuh Gah Canoe La	Good	Cosmetic	11-15	Needs clearing out
Gate 1	Shuh Shuh Gah Canoe La	Good	Cosmetic	11-15	The gate is bent but functional. The hook that holds it open needs to be adjusted the gate was swinging loose, needs paint
Asphalt trail	Shuh Shuh Gah Canoe La	Good	Cosmetic	11-15	Cracking at the end where it meets the gravel road
River map sign	Shuh Shuh Gah Canoe La	Excellent	None	16-20	
Water	Shuh Shuh Gah Canoe La				
Fishing	Shuh Shuh Gah Canoe La				

Information	Subat F.P.	Poor	Replacement	0-5	No sign
Restroom	Subat F.P.	Fair	Structural Repairs	6-10	Window needs to be replaced, restroom sign needs replacing, paint job.
Water	Subat F.P.	Fair	Structural Repairs	6-10	Very difficult to operate, needs a paint job
Parking	Subat F.P.	Good	Cosmetic	11-15	A few potholes, some cracked parking blocks
Observation Area	Subat F.P.	Good	Cosmetic	11-15	A few boards to replace, conservation area sign needs replacing
Crushed limestone trail	Subat F.P.	Good	A little crushed lime in	11-15	
Sign	Subat F.P.	Good	Cosmetic	11-15	
Shelter	Subat F.P.	Good	Cosmetic	11-15	
Gate	Subat F.P.	Good	Cosmetic	11-15	
Turf trail	Subat F.P.	Excellent	None	16-20	

