

COUNTY OF KENDALL, ILLINOIS COMMITTEE OF THE WHOLE Kendall County Office Building, 111 W. Fox Street County Board Room 209, Yorkville, IL 60560 Thursday, February 15, 2024 at 4:00 p.m. MEETING AGENDA

- 1. Call to Order and Pledge of Allegiance
- 2. Roll Call: Matt Kellogg (Chairman), Scott Gengler (Vice-Chair), Zach Bachmann, Brian DeBolt, Elizabeth Flowers, Dan Koukol, Jason Peterson, Ruben Rodriguez, Brooke Shanley, Seth Wormley
- 3. * MOTION (VV) Approval of Agenda
- 4. *MOTION (Forward to County Board): Approval of Claims
- 5. Committee Reports and Updates
 - A. <u>Presentation</u>: January Monthly Update of COB II Construction. Pg 2.
- 6. New Committee Business
 - A. *MOTION (Forward to County Board): Approval of Contingency Reduction No.5 Omega Plumbing; \$144,702 (\$2,202 increase) CSN Electric \$998,633 (\$8,852, \$9,808 & \$1,851 increases). Pg 94.
 - *MOTION (Forward to County Board): Approval of Phase 1 Office, Lobby and Training Furniture procurement via the TIPS government Co-Op Contract Number 210305 at a cost notto-exceed \$310,648. Pg 96.
- 7. Old Committee Business
- 8. Department Head and Elected Official Reports
- 9. Public Comment
- 10. Questions from the Media
- 11. Chairman's Report

Appointments

Mike Nadeau - Little Rock-Fox Fire District - 3 year term - February 2027 Mike Homerding - Farmland Review Committee - No term limit Melinda Tejada – 708 Mental Health Board – 4 year term – February 2028 Pam Ely – 708 Mental Health Board – 4 year term – February 2028 Seth Wormley – Connect Kendall County Commission – 2 years term – November 2024

- 12. Action Items for County Board
- 13. Executive Session
- 14. Adjournment

If special accommodations or arrangements are needed to attend this County meeting, please contact the Administration Office at 630-553-4171, a minimum of 24-hours prior to the meeting time

MONTHLY PROGRESS REPORT

KENDALL COUNTY NEW OFFICE BUILDING

JANUARY 2024









January Monthly Report

Construction Management Services

February 2024

Contents

Section 1: Project Update

Section 2: Project Cost Report

Section 3: Schedule

Section 4: Construction Field Reports and Photos

Section 5: Architectural & Engineering Field Reports

SECTION 1: PROJECT UPDATE



Kendall County

New Office Building

Monthly Project Summary 1/31/24 Work Completed in January 2024

To date we have completed the following activities:

- Structural Steel/Light Gauge Trusses
- Roof Deck

We are currently progressing on the following activities:

- AV Barrier/Water Proofing Membrane
- Roofing
- Concrete ADA ramp at South Lot Retaining Wall
- Rough In Mechanical Piping & Ductwork
- Fire Protection Piping
- Rough In Electrical
- Rough In Plumbing
- HVAC Equipment Install & Hookup
- Drywall Deck Framing, Insulation, Drywall

The following phases of construction scheduled for the near future:

- Rough Framing
- Windows
- Install Doorframes
- Drywall


SECTION 2: PROJECT COST REPORT



Kendall County – New Office Building

Cost Report & Contingency Reductions Through 01/31/2024

PCO #	Date Approve d By Owner	Contractor	Description	Potential Contingency Reduction Amount	Contingency Reduction Amount Approved	Comments
			CONTINGENCY REDUCTIONS APPROVED	IN OCTOBER:		\$45,035
		CONT		\$75,448		
		CON		\$6,580		
		CO	ANUARY 2024:		\$145,632	
		CSN Electric	PR-004 Electrical Changes & ASI-012 credit	\$8,852	\$8,852	Coordination of submitted items, products, and equipment.
		CSN Electric	PR-005 Wiremold and Floor Boxes	\$9,808	\$9,808	Required by Voter layout changes
		CSN Electric	ASI-009 Elevator Electrical Changes	\$1,851	\$1,851	Elevator requirements
		Omega Plumbing	PR-007 Lower water main to accommodate other equipment	\$2,202	\$2,202	Connection to water main in sprinkler room
		CONTINGE	NCY REDUCTIONS TO BE APPROVED IN FEI	BRUARY 2024:		\$22,713








ID	Task Name	Duration	Start	Finish	Jan '24		Feb '24	Mar '24 Apr '24
1	Kendall Co Phase 1 County Building Project	374 days	Mon 9/5/22	Thu 2/8/24	1/14 1/21 1/28 ndall Co Phase 1 County Build		2/11 2/18 2/25 ct ■ 2/8	3/3 3/10 3/17 3/24 3/31 4/7 4/14
2	Schematic Design Updates	57 days	Mon 9/5/22	Tue 11/22/22	2			
8	Design Development	90 days	Wed 11/23/22	2 Tue 3/28/23				
15	Construction Documents	83 days	Thu 12/29/22	Mon 4/24/23				
25	Fast Track Bidding	76 days	Tue 3/14/23	Tue 6/27/23				
23	Permitting	70 days	Wed 4/19/23	Tue 7/25/23				
33	Shops & Procurement	162 days	Wed 6/28/23	Thu 2/8/24	Shops & Procuremer	nt	- ▼ 2/8	
70	Construction	266 days	Wed 5/31/23	Wed 6/5/24				Construction
71	Mobilization	26 days	Wed 5/31/23	Wed 7/5/23				
89	Earth Excavation/Foundations	72 days	Mon 7/17/23	Tue 10/24/23	3			
95	Building Shell	152 days	Mon 9/18/23	Tue 4/16/24				4 /
96	Rough-in Underground Plumbing/Electric	8 days	Mon 9/18/23	Wed 9/27/23				
97	Stone/Prep basement floor SOG	2 days	Thu 9/28/23	Fri 9/29/23				
98	Pour Basement Floor Slab	2 days	Mon 10/2/23	Tue 10/3/23				
99	Basement/Elevator Shaft CMU Install	5 days	Wed 10/4/23	Tue 10/10/23	3			
100	1st Floor PC Plank	7 days	Wed 10/11/23	3 Thu 10/19/23	3			
101	1st Floor SOG & Plank Topping	4 days	Wed 11/1/23	Mon 11/6/23				
102	LG Bearing Wall Framing	15 days	Mon 11/6/23	Fri 11/24/23				
103	Structural Steel/LG Trusses	25 days	Mon 11/20/23	Fri 12/22/23				
108	Roof Deck	10 days	Thu 12/21/23	Wed 1/3/24				
109	Roofing (Ice & Water)	4 days	Tue 1/2/24	Fri 1/5/24				
110	Roofing (Shingles)	3 days	Wed 1/24/24	Fri 1/26/24	Roofing (Shingles) 1/24 1/26			
106	AVM Install	5 days	Fri 2/9/24	Thu 2/15/24		2/9	AVM Install 2/15	
104	Windows	8 days	Mon 2/12/24	Wed 2/21/24			Windows 2/12 2/21	
111	Roof OH Returns (Framing/deck/shingles)	3 days	Fri 2/16/24	Tue 2/20/24		Roo	f OH Returns (Framing/deck/shingles) 2/16 2/20	
107	Masonry Veneer/Stone	15 days	Mon 3/25/24	Fri 4/12/24				Masonry Veneer/Stone 3/25 4/12
105	Storefront	8 days	Fri 4/5/24	Tue 4/16/24				Storefront 4/5
75	Site Utilities & Parking Lot Work	152 days	Mon 9/25/23	Tue 4/23/24	ot Work			
76	Sanitary Sewer	5 days	Mon 9/25/23	Fri 9/29/23				
79	Parking Lot Retaining Wall	7 days	Mon 9/25/23	Tue 10/3/23				
77	Storm Sewer	5 days	Mon 10/2/23	Fri 10/6/23				
78	Water Main	7 days	Wed 10/25/23	3 Thu 11/2/23				
80	Curbs & Gutter - South Lot	2 days	Mon 11/6/23	Tue 11/7/23				
81	Parking Lot Stone - South Lot	2 days	Wed 11/8/23	Thu 11/9/23				
	I			1	1		· · · · · · · · · · · · · · · · · · ·	

or '24 4/14 4/21 4	May '24 28 5/5 5/12	5/19 5/26	6/2
4/14 4/21 4	28 5/5 5/12	5/19 5/26	6/2
		1	
		1	
		1	
		1	
			6/5
			• 0,0
		1	
		1	
/// 0		1	
━♥ 4/16			
		1	
		1	
		1	
		1	
		1	
		1	
		1	
2		 	
4/16			
		1	
₩ 4/23			
		1	
		1	
		1	
		1	
		1	



	Task Name	Duration	Start	Finish	24 Feb '24 Mar '24 /14 1/21 1/28 2/4 2/11 2/18 2/25 3/3 3/10 3/17 3/24	Apr ' 4 3/31 4/7
82	Asphalt Binder - South Lot	2 days	Fri 11/10/23	Mon 11/13/23		
83	Demo Existing West Lot & Fill	5 days	Tue 11/14/23			
84	Curbs & Gutter - West Lot	2 days	Thu 11/23/23	Fri 11/24/23		
35	Parking Lot Stone - West Lot	2 days	Mon 11/27/23	Tue 11/28/23		
36	Asphalt Binder - West Lot	2 days	Wed 11/29/23	3 Thu 11/30/23		
37	Asphalt Wear Course & Striping	3 days	Wed 4/10/24	Fri 4/12/24		Asphalt Wear Course & 4/10 4/12
88	Final Concrete Flatwork/Planter & Landscaping	10 days	Wed 4/10/24	Tue 4/23/24		Final Concrete Flatwor 4/10
12	Interior MEP, Carpentry and Finishes	100 days	6 Mon 1/8/24	Fri 5/24/24	Interior MEP, Carpentry and Finisher	
13	Rough Framing	30 days	Mon 1/8/24	Fri 2/16/24	Rough Framing 2/16	
15	Rough in Mechanical Piping and Ductwork	40 days	Mon 1/8/24	Fri 3/1/24	Rough in Mechanical Piping and Ductwork	
16	Rough in Electric and Plumbing	35 days	Mon 1/8/24	Fri 2/23/24	Rough in Electric and Plumbing 2/23	
19	Drywall (Bot. of Trusses)	21 days	Mon 1/15/24	Mon 2/12/24	Drywall (Bot. of Trusses)	
14	Fire Protection Piping	12 days	Mon 2/12/24	Tue 2/27/24	Fire Protection Piping	
20	Drywall Install	15 days	Wed 2/14/24	Tue 3/5/24	2/12 2/27 Drywall Install	
8	Install Door Frames	3 days	Mon 2/19/24	Wed 2/21/24	2/14 3/5 Install Door Frames	
21	Drywall Taping & Finishing	12 days	Tue 2/27/24	Wed 3/13/24	2/19 2/21 Drywall Taping & Finishing 2/27 2/27 3/13	
17	HVAC Equipment Install and Hookups	15 days	Mon 3/4/24	Fri 3/22/24	HVAC Equipment Install and Hookups	
22	Painting			Fri 3/29/24	3/4 3/22 Painting	
3	Ceilings			Fri 4/5/24		Ceilings
4	Flooring		Mon 4/1/24	Tue 4/16/24	3/25	4/5 Flooring
28	MEP Trim Work		Mon 4/1/24	Fri 5/3/24		4/1 MEP
25	Casework		Wed 4/10/24			4/1 Ca
:6	Doors/Finished Carpentry		Wed 4/10/24			4/10 Doors
29	Paint Touch-ups & Final Finishes		Mon 4/29/24			4/10
27	·		Mon 5/20/24			
34			Mon 5/6/24	Wed 6/5/24		
35	Technology Implementation		Mon 5/6/24	Fri 5/17/24		
36	FF&E Installation	5 days	Wed 5/22/24			
7	Move-In		Wed 5/22/24 Wed 5/29/24			
8	First Day of Operations	5 days	Wed 5/29/24 Wed 6/5/24	Wed 6/5/24		
30		1 day				
31	Project Close-Out		Mon 5/13/24			
	Punchlist	5	Mon 5/13/24			
32	Inspections/Testing/Training	5 days	Mon 5/27/24			
33	Substantial Completion	1 day	Mon 6/3/24	Mon 6/3/24		





SECTION 4: CONSTRUCTION FIELD REPORTS AND PHOTOS



#92: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 3, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 3, 2024, 4:13 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information





1. Work Log

	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	4	32	crew worked on roof deck, fascia and hanging of dens glass today
	BP #13 Electrical - CSN Electric	2	16	crew worked on piping in basement today
	BP #12 Mechanical - Jensen's Plumbing & Heating	1	8	crew worked on coring through the concrete for piping penetrations
Totals		7	56	

Photos (12)



IMG_0874 **Taken on** Jan 2, 2024, 9:27 AM CST **Added on** Jan 3, 2024, 4:12 PM CST **Added by** Ken Gleason



IMG_0875 **Taken on** Jan 2, 2024, 9:27 AM CST **Added on** Jan 3, 2024, 4:12 PM CST **Added by** Ken Gleason



IMG_0882 **Taken on** Jan 2, 2024, 1:11 PM CST **Added on** Jan 3, 2024, 4:12 PM CST **Added by** Ken Gleason



IMG_0883 **Taken on** Jan 2, 2024, 1:12 PM CST **Added on** Jan 3, 2024, 4:12 PM CST **Added by** Ken Gleason

Form detail report



IMG_0879 **Taken on** Jan 2, 2024, 9:27 AM CST **Added on** Jan 3, 2024, 4:12 PM CST **Added by** Ken Gleason



IMG_0884 **Taken on** Jan 2, 2024, 1:13 PM CST **Added on** Jan 3, 2024, 4:12 PM CST **Added by** Ken Gleason



IMG_0880 **Taken on** Jan 2, 2024, 9:32 AM CST **Added on** Jan 3, 2024, 4:13 PM CST **Added by** Ken Gleason



IMG_0885 **Taken on** Jan 3, 2024, 10:17 AM CST **Added on** Jan 3, 2024, 4:13 PM CST **Added by** Ken Gleason



IMG_0878 **Taken on** Jan 2, 2024, 9:27 AM CST **Added on** Jan 3, 2024, 4:13 PM CST **Added by** Ken Gleason



IMG_0877 **Taken on** Jan 2, 2024, 9:27 AM CST **Added on** Jan 3, 2024, 4:13 PM CST **Added by** Ken Gleason



IMG_0881 **Taken on** Jan 2, 2024, 9:32 AM CST **Added on** Jan 3, 2024, 4:13 PM CST **Added by** Ken Gleason



IMG_0876 **Taken on** Jan 2, 2024, 9:27 AM CST **Added on** Jan 3, 2024, 4:13 PM CST **Added by** Ken Gleason

#93: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 4, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 4, 2024, 3:40 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information



1. Work Log

	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	4	32	crew worked fascia boards and dens glass today
	BP #10 Fire Protection - CL Doucette Inc	1	8	worked on piping in basement and hangers on first floor
	BP #12 Mechanical - Jensen's Plumbing & Heating	3	24	crew worked on piping in basement
	BP #13 Electrical - CSN Electric	1	8	worked on piping in basement
Totals		9	72	

Photos (2)



IMG_0889 **Taken on** Jan 4, 2024, 2:56 PM CST **Added on** Jan 4, 2024, 3:40 PM CST **Added by** Ken Gleason



IMG_0888 **Taken on** Jan 4, 2024, 2:56 PM CST **Added on** Jan 4, 2024, 3:40 PM CST **Added by** Ken Gleason



#95: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 8, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 8, 2024, 2:56 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information





1. Work Log

	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	4	32	crew worked on dens glass at north side of site and site clean up today
	BP #6 Masonry - Jimmy'z Masonry	1	8	worked on stair pockets at basement level stairway
	BP #12 Mechanical - Jensen's Plumbing & Heating	2	16	crew worked on vent lines and piping and ductwork basement and first floor
	BP #13 Electrical - CSN Electric	2	16	crew worked on pumping out elevator pit area and continued with lighting for basement
Totals		9	72	

Photos (4)



IMG_0904 **Taken on** Jan 8, 2024, 10:54 AM CST **Added on** Jan 8, 2024, 2:56 PM CST **Added by** Ken Gleason



IMG_0905 **Taken on** Jan 8, 2024, 10:57 AM CST **Added on** Jan 8, 2024, 2:56 PM CST **Added by** Ken Gleason



IMG_0902 **Taken on** Jan 8, 2024, 10:52 AM CST **Added on** Jan 8, 2024, 2:56 PM CST **Added by** Ken Gleason



IMG_0903 **Taken on** Jan 8, 2024, 10:54 AM CST **Added on** Jan 8, 2024, 2:56 PM CST **Added by** Ken Gleason



#96: Daily Report





Forms

Location	Kendall County New Office Building
Form date	Jan 9, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 10, 2024, 12:27 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information

Weather					
▲ Rain: 0.9	94 inches				Weather View Sources
7:00 AM	Snow	12:00 PM	Heavy Snow	4:00 PM	Snow
JYL	Temperature: 33°F	JYL	Temperature: 34°F	JYL	Temperature: 34°F
%	Wind: – 10mph		Wind: 🖌 7mph		Wind: ↓ 7mph
· 小 ·	Humidity: 96%	'ጥ'	Humidity: 95%	'ጥ'	Humidity: 94%



1. Work Log

22-1071	(BUILD)	Kendall C	ounty PH1	Clerk Bui	lding		

	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	4	32	crew worked on closing up building at eaves to help prevent heat loss of temp heat to melt snow from roof as well as interior cleanup and removal of wall ties
	BP #12 Mechanical - Jensen's Plumbing & Heating	2	16	crew worked on mechanical piping in basement
	BP #13 Electrical - CSN Electric	2	16	crew worked on electrical piping and wiring in basement for lighting
Totals		8	64	

Photos (11)



IMG_0908 **Taken on** Jan 9, 2024, 11:08 AM CST **Added on** Jan 9, 2024, 3:42 PM CST **Added by** Ken Gleason



IMG_0909 **Taken on** Jan 9, 2024, 11:08 AM CST **Added on** Jan 9, 2024, 3:42 PM CST **Added by** Ken Gleason



IMG_0907 **Taken on** Jan 9, 2024, 11:08 AM CST **Added on** Jan 9, 2024, 3:42 PM CST **Added by** Ken Gleason



IMG_0911 **Taken on** Jan 9, 2024, 11:09 AM CST **Added on** Jan 9, 2024, 3:42 PM CST **Added by** Ken Gleason





IMG_0906 **Taken on** Jan 9, 2024, 11:02 AM CST **Added on** Jan 9, 2024, 3:42 PM CST **Added by** Ken Gleason



IMG_0912 **Taken on** Jan 9, 2024, 11:09 AM CST **Added on** Jan 10, 2024, 12:27 PM CST **Added by** Ken Gleason



IMG_0913 **Taken on** Jan 9, 2024, 11:09 AM CST **Added on** Jan 9, 2024, 3:42 PM CST **Added by** Ken Gleason



IMG_0910 **Taken on** Jan 9, 2024, 11:08 AM CST **Added on** Jan 10, 2024, 12:27 PM CST **Added by** Ken Gleason




22-1071 (BUILD) Kendall County PH1 Clerk Building



IMG_0914 **Taken on** Jan 9, 2024, 11:09 AM CST **Added on** Jan 10, 2024, 12:27 PM CST **Added by** Ken Gleason



IMG_0915 **Taken on** Jan 9, 2024, 11:13 AM CST **Added on** Jan 10, 2024, 12:27 PM CST **Added by** Ken Gleason



IMG_0916 **Taken on** Jan 9, 2024, 11:13 AM CST **Added on** Jan 10, 2024, 12:27 PM CST **Added by** Ken Gleason

27

#97: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 10, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 10, 2024, 1:07 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information





Heating

Electric

BP #13 Electrical - CSN

1.1 ...

Totals

1. Work Log					
	Crew	# Workers	# Total hours	Work performed	
	BP #2 General Trades - Lite Construction	4	32	crew worked on site clean up and closing up the eaves for temp,heat retainage to try and heat/ melt snow from the roof to get the ice/water shield completed at the ridge	
	BP #12 Mechanical - Jensen's Plumbing &	2	16	crew worked on mechanical piping in	

2

8

16

64

basement

basement

crew worked on piping and

temp heat set up for

Photos (8)



IMG_0917 **Taken on** Jan 10, 2024, 12:45 PM CST **Added on** Jan 10, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0921 **Taken on** Jan 10, 2024, 12:49 PM CST **Added on** Jan 10, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0923 **Taken on** Jan 10, 2024, 12:50 PM CST **Added on** Jan 10, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0919 **Taken on** Jan 10, 2024, 12:45 PM CST **Added on** Jan 10, 2024, 1:07 PM CST **Added by** Ken Gleason



Form detail report



IMG_0918 **Taken on** Jan 10, 2024, 12:45 PM CST **Added on** Jan 10, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0922 **Taken on** Jan 10, 2024, 12:50 PM CST **Added on** Jan 10, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0924 **Taken on** Jan 10, 2024, 12:50 PM CST **Added on** Jan 10, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0920 **Taken on** Jan 10, 2024, 12:46 PM CST **Added on** Jan 10, 2024, 1:07 PM CST **Added by** Ken Gleason


#98: Daily Report





Forms Kendall County New Office Building Location Form date Jan 11, 2024 Submitted by **Ken Gleason** Closed **Status** Last update Jan 11, 2024, 1:50 PM CST Last updated by **Ken Gleason Included references** Assets | Files | Forms | Issues | Photos

Supporting information





1. Work Log		

	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	4	32	crew worked on temp heat coverage for the roof. started working on interior layout of walls.
	BP #12 Mechanical - Jensen's Plumbing & Heating	2	16	crew worked on external mechanical hook ups today
	BP #13 Electrical - CSN Electric	2	16	crew worked on basement temp heat and piping connections in basement
Totals		8	64	

Photos (6)



IMG_0930 **Taken on** Jan 11, 2024, 9:20 AM CST **Added on** Jan 11, 2024, 1:50 PM CST **Added by** Ken Gleason



IMG_0929 **Taken on** Jan 11, 2024, 9:20 AM CST **Added on** Jan 11, 2024, 1:50 PM CST **Added by** Ken Gleason



IMG_0928 **Taken on** Jan 11, 2024, 9:19 AM CST **Added on** Jan 11, 2024, 1:50 PM CST **Added by** Ken Gleason



IMG_0926 **Taken on** Jan 11, 2024, 9:16 AM CST **Added on** Jan 11, 2024, 1:50 PM CST **Added by** Ken Gleason





IMG_0925 **Taken on** Jan 11, 2024, 9:16 AM CST **Added on** Jan 11, 2024, 1:50 PM CST **Added by** Ken Gleason



IMG_0927 **Taken on** Jan 11, 2024, 9:17 AM CST **Added on** Jan 11, 2024, 1:50 PM CST **Added by** Ken Gleason



#99: Daily Report





Forms

Location	Kendall County New Office Building
Form date	Jan 12, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 12, 2024, 4:20 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information

Weather					
▲ Rain: 0.9	94 inches				Weather View Sources
7:00 AM	Heavy Snow	12:00 PM	Snow	4:00 PM	Snow
JYL	Temperature: 32°F	JYL	Temperature: 34°F	JYL	Temperature: 34°F
	Wind: – 16mph		Wind: ← 10mph		Wind: 🖌 4mph
'ጥ'	Humidity: 96%	'ጥ'	Humidity: 95%	. ተ.	Humidity: 96%
Updated Jan ´	17, 2024 at 5:55 PM				



Notes

Friday 1/12/24 was a snow day for all trades. There were no trades on site today due to the inclement weather.




#100: Daily Report





FormsLocationKendall County New Office BuildingForm dateJan 15, 2024Submitted byKen GleasonStatusClosedLast updateJan 15, 2024, 1:45 PM CSTLast updated byKen GleasonIncluded referencesAssets | Files | Forms | Issues | Photos

Supporting information



	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	2	16	crew worked on framing bathroom in basement today
	BP #12 Mechanical - Jensen's Plumbing & Heating	1	8	worked on insulating mechanical ductwork on site for Jensens
	BP #13 Electrical - CSN Electric	2	16	crew worked on piping in basement mechanical room
Totals		5	40	

Photos (8)



IMG_0936 **Taken on** Jan 15, 2024, 10:49 AM CST **Added on** Jan 15, 2024, 1:45 PM CST **Added by** Ken Gleason



IMG_0934 **Taken on** Jan 15, 2024, 10:48 AM CST **Added on** Jan 15, 2024, 1:45 PM CST **Added by** Ken Gleason



IMG_0931 **Taken on** Jan 15, 2024, 10:40 AM CST **Added on** Jan 15, 2024, 1:45 PM CST **Added by** Ken Gleason



IMG_0935 **Taken on** Jan 15, 2024, 10:49 AM CST **Added on** Jan 15, 2024, 1:45 PM CST **Added by** Ken Gleason




22-1071 (BUILD) Kendall County PH1 Clerk Building



IMG_0937 **Taken on** Jan 15, 2024, 10:49 AM CST **Added on** Jan 15, 2024, 1:45 PM CST **Added by** Ken Gleason



IMG_0933 **Taken on** Jan 15, 2024, 10:42 AM CST **Added on** Jan 15, 2024, 1:45 PM CST **Added by** Ken Gleason



IMG_0938 **Taken on** Jan 15, 2024, 10:49 AM CST **Added on** Jan 15, 2024, 1:45 PM CST **Added by** Ken Gleason



IMG_0932 **Taken on** Jan 15, 2024, 10:40 AM CST **Added on** Jan 15, 2024, 1:45 PM CST **Added by** Ken Gleason

#101: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 16, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 16, 2024, 3:27 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information





	Crew	# Workers	# Total hours	Work performed
	BP #13 Electrical - CSN Electric	2	16	crew worked on basement piping and electric
	BP #12 Mechanical - Jensen's Plumbing & Heating	2	16	crew worked on piping in basement and to mechanical units on exterior pad
Totals		4	32	

Photos (2)



IMG_0940 **Taken on** Jan 16, 2024, 8:55 AM CST **Added on** Jan 16, 2024, 3:27 PM CST **Added by** Ken Gleason



IMG_0939 **Taken on** Jan 16, 2024, 8:55 AM CST **Added on** Jan 16, 2024, 3:27 PM CST **Added by** Ken Gleason

#102: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 17, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 17, 2024, 1:17 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information



	Crew	# Workers	# Total hours	Work performed
	BP #12 Mechanical - Jensen's Plumbing & Heating	2	16	crew worked on mechanical piping in basement today
	BP #13 Electrical - CSN Electric	1	8	worked on electrical piping in basement
Totals		3	24	

Photos (5)



IMG_0945 **Taken on** Jan 17, 2024, 1:12 PM CST **Added on** Jan 17, 2024, 1:17 PM CST **Added by** Ken Gleason



IMG_0942 **Taken on** Jan 17, 2024, 1:11 PM CST **Added on** Jan 17, 2024, 1:17 PM CST **Added by** Ken Gleason



IMG_0946 **Taken on** Jan 17, 2024, 1:12 PM CST **Added on** Jan 17, 2024, 1:17 PM CST **Added by** Ken Gleason



IMG_0943 **Taken on** Jan 17, 2024, 1:12 PM CST **Added on** Jan 17, 2024, 1:17 PM CST **Added by** Ken Gleason



IMG_0944 **Taken on** Jan 17, 2024, 1:12 PM CST **Added on** Jan 17, 2024, 1:17 PM CST **Added by** Ken Gleason



#103: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 18, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 18, 2024, 1:07 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information





	Crew	# Workers	# Total hours	Work performed
	BP #13 Electrical - CSN Electric	2	16	crew worked on electrical piping in basement
	BP #12 Mechanical - Jensen's Plumbing & Heating	2	16	crew worked on mechanical piping in basement and on mechanical pad at east of site
Totals		4	32	


Photos (7)



IMG_0952 **Taken on** Jan 18, 2024, 9:30 AM CST **Added on** Jan 18, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0951 **Taken on** Jan 18, 2024, 9:29 AM CST **Added on** Jan 18, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0954 **Taken on** Jan 18, 2024, 9:55 AM CST **Added on** Jan 18, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0950 **Taken on** Jan 18, 2024, 9:29 AM CST **Added on** Jan 18, 2024, 1:07 PM CST **Added by** Ken Gleason





IMG_0953 **Taken on** Jan 18, 2024, 9:34 AM CST **Added on** Jan 18, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0949 **Taken on** Jan 18, 2024, 9:29 AM CST **Added on** Jan 18, 2024, 1:07 PM CST **Added by** Ken Gleason



IMG_0955 **Taken on** Jan 18, 2024, 9:55 AM CST **Added on** Jan 18, 2024, 1:07 PM CST **Added by** Ken Gleason



#105: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 23, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 23, 2024, 3:35 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information





	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	2	16	crew worked on moving fencing for west parking lot and snow and ice clearing of remainder of west lot and east side of site basement parking area
	BP #12 Mechanical - Jensen's Plumbing & Heating	2	16	crew worked on piping in basement and exterior at mechanical pad.
	BP #13 Electrical - CSN Electric	2	16	crew worked on electrical piping in basement
Totals		6	48	



Photos (14)



IMG_0981 **Taken on** Jan 23, 2024, 10:33 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0975 **Taken on** Jan 23, 2024, 10:22 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0978 **Taken on** Jan 23, 2024, 10:22 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0977 **Taken on** Jan 23, 2024, 10:22 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason





IMG_0980 **Taken on** Jan 23, 2024, 10:25 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0976 **Taken on** Jan 23, 2024, 10:22 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0979 **Taken on** Jan 23, 2024, 10:23 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0974 **Taken on** Jan 23, 2024, 10:21 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0982 **Taken on** Jan 23, 2024, 10:33 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0983 **Taken on** Jan 23, 2024, 10:34 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0984 **Taken on** Jan 23, 2024, 10:34 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0985 **Taken on** Jan 23, 2024, 10:34 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason





IMG_0987 **Taken on** Jan 23, 2024, 10:35 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



IMG_0986 **Taken on** Jan 23, 2024, 10:35 AM CST **Added on** Jan 23, 2024, 3:35 PM CST **Added by** Ken Gleason



#106: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 24, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 24, 2024, 1:04 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information





	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	2	16	crew worked on front entryway barrel vaulted ceiling area
	BP #13 Electrical - CSN Electric	2	16	crew worked on electrical piping in basement
	BP #12 Mechanical - Jensen's Plumbing & Heating	2	16	crew worked on mechanical piping in basement and mechanical pad at exterior
Totals		6	48	

Photos (10)



IMG_0991 **Taken on** Jan 24, 2024, 11:12 AM CST **Added on** Jan 24, 2024, 1:03 PM CST **Added by** Ken Gleason



IMG_0995 **Taken on** Jan 24, 2024, 11:18 AM CST **Added on** Jan 24, 2024, 1:03 PM CST **Added by** Ken Gleason



IMG_0997 **Taken on** Jan 24, 2024, 11:18 AM CST **Added on** Jan 24, 2024, 1:03 PM CST **Added by** Ken Gleason




IMG_0990 **Taken on** Jan 24, 2024, 11:11 AM CST **Added on** Jan 24, 2024, 1:03 PM CST **Added by** Ken Gleason



IMG_0988 **Taken on** Jan 24, 2024, 11:07 AM CST **Added on** Jan 24, 2024, 1:03 PM CST **Added by** Ken Gleason



IMG_0989 **Taken on** Jan 24, 2024, 11:11 AM CST **Added on** Jan 24, 2024, 1:03 PM CST **Added by** Ken Gleason



IMG_0996 **Taken on** Jan 24, 2024, 11:18 AM CST **Added on** Jan 24, 2024, 1:04 PM CST **Added by** Ken Gleason



IMG_0992 **Taken on** Jan 24, 2024, 11:12 AM CST **Added on** Jan 24, 2024, 1:04 PM CST **Added by** Ken Gleason



Form detail report

22-1071 (BUILD) Kendall County PH1 Clerk Building



IMG_0993 **Taken on** Jan 24, 2024, 11:13 AM CST **Added on** Jan 24, 2024, 1:04 PM CST **Added by** Ken Gleason



IMG_0994 **Taken on** Jan 24, 2024, 11:14 AM CST **Added on** Jan 24, 2024, 1:04 PM CST **Added by** Ken Gleason




#107: Daily Report





FormsLocationKendall County New Office BuildingForm dateJan 25, 2024Submitted byKen GleasonStatusClosedLast updateJan 25, 2024, 2:19 PM CSTLast updated byKen GleasonIncluded referencesAssets | Files | Forms | Issues | Photos

Supporting information





	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	2	16	crew worked on chimneys and vestibule area of roof at front entry
	BP #13 Electrical - CSN Electric	2	16	crew worked on electrical piping in basement
Totals		4	32	

Form detail report

Photos (6)



IMG_1001 **Taken on** Jan 25, 2024, 9:35 AM CST **Added on** Jan 25, 2024, 2:19 PM CST **Added by** Ken Gleason



IMG_1002 **Taken on** Jan 25, 2024, 9:39 AM CST **Added on** Jan 25, 2024, 2:19 PM CST **Added by** Ken Gleason



IMG_1005 **Taken on** Jan 25, 2024, 9:40 AM CST **Added on** Jan 25, 2024, 2:19 PM CST **Added by** Ken Gleason



IMG_1004 **Taken on** Jan 25, 2024, 9:40 AM CST **Added on** Jan 25, 2024, 2:19 PM CST **Added by** Ken Gleason





IMG_1003 **Taken on** Jan 25, 2024, 9:39 AM CST **Added on** Jan 25, 2024, 2:19 PM CST **Added by** Ken Gleason



IMG_1006 **Taken on** Jan 25, 2024, 9:41 AM CST **Added on** Jan 25, 2024, 2:19 PM CST **Added by** Ken Gleason

#109: Daily Report






Forms

Location	Kendall County New Office Building
Form date	Jan 29, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 29, 2024, 2:25 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information





Crew	# Workers	# Total hours
BP #2 General Trades - Lite Construction	5	40
BP #4 Building Concrete - Premium Concrete Inc	4	20
BP #13 Electrical - CSN Electric	2	16
BP #12 Mechanical - Jensen's Plumbing & Heating	2	16
BP #7 Roofing - Filotto Roofing	4	32

Totals

17

124

Work performed

crew worked on fascia at exterior east as well as roof overhangs. ceiling deck plastic and insulation started today as well.

crew worked on setting forms for the ramp work at south parking lot retaining

crew moved to the first floor today to start running their electrical piping and

mechanical piping in the

crew worked on roofing today, ice and water shield completion and shingle

wall

boxes

crew worked on

basement

installation

Photos (8)



IMG_1024 **Taken on** Jan 29, 2024, 8:43 AM CST **Added on** Jan 29, 2024, 2:24 PM CST **Added by** Ken Gleason



IMG_1025 **Taken on** Jan 29, 2024, 8:49 AM CST **Added on** Jan 29, 2024, 2:24 PM CST **Added by** Ken Gleason



IMG_1027 **Taken on** Jan 29, 2024, 8:49 AM CST **Added on** Jan 29, 2024, 2:24 PM CST **Added by** Ken Gleason



IMG_1023 **Taken on** Jan 29, 2024, 8:31 AM CST **Added on** Jan 29, 2024, 2:25 PM CST **Added by** Ken Gleason



IMG_1029 **Taken on** Jan 29, 2024, 8:54 AM CST **Added on** Jan 29, 2024, 2:25 PM CST **Added by** Ken Gleason



IMG_1022 **Taken on** Jan 29, 2024, 8:28 AM CST **Added on** Jan 29, 2024, 2:25 PM CST **Added by** Ken Gleason



IMG_1026 **Taken on** Jan 29, 2024, 8:49 AM CST **Added on** Jan 29, 2024, 2:25 PM CST **Added by** Ken Gleason



IMG_1028 **Taken on** Jan 29, 2024, 8:53 AM CST **Added on** Jan 29, 2024, 2:25 PM CST **Added by** Ken Gleason


#110: Daily Report





FormsLocationKendall County New Office BuildingForm dateJan 30, 2024Submitted byKen GleasonStatusClosedLast updateJan 30, 2024, 3:50 PM CSTLast updated byKen GleasonIncluded referencesAssets | Files | Forms | Issues | Photos

Supporting information





1. Work Log

	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	5	40	crew worked on exterior fascia as well as interior plastic on roof deck.
	BP #6 Masonry - Jimmy'z Masonry	1	8	worked on exterior av barrier at window openings
	BP #7 Roofing - Filotto Roofing	4	32	crew worked on roof shingles today
	BP #12 Mechanical - Jensen's Plumbing & Heating	1	8	crew worked on mechanical piping in. basement today
	BP #13 Electrical - CSN Electric	1	8	crew worked on first floor electrical piping
Totals		12	96	

References

Photos (13)



IMG_1033 **Taken on** Jan 30, 2024, 11:42 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1034 **Taken on** Jan 30, 2024, 11:43 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1031 **Taken on** Jan 30, 2024, 11:41 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1035 **Taken on** Jan 30, 2024, 11:43 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason

Form detail report



IMG_1036 **Taken on** Jan 30, 2024, 11:48 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1032 **Taken on** Jan 30, 2024, 11:41 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1038 **Taken on** Jan 30, 2024, 11:59 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1037 **Taken on** Jan 30, 2024, 11:48 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason

Form detail report



IMG_1030 **Taken on** Jan 30, 2024, 11:41 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1040 **Taken on** Jan 30, 2024, 12:00 PM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1039 **Taken on** Jan 30, 2024, 11:59 AM CST **Added on** Jan 30, 2024, 3:49 PM CST **Added by** Ken Gleason



IMG_1042 **Taken on** Jan 30, 2024, 12:00 PM CST **Added on** Jan 30, 2024, 3:50 PM CST **Added by** Ken Gleason





IMG_1041 **Taken on** Jan 30, 2024, 12:00 PM CST **Added on** Jan 30, 2024, 3:50 PM CST **Added by** Ken Gleason



Form detail

#111: Daily Report



Form detail report




Forms

Location	Kendall County New Office Building
Form date	Jan 31, 2024
Submitted by	Ken Gleason
Status	Closed
Last update	Jan 31, 2024, 1:21 PM CST
Last updated by	Ken Gleason
Included references	Assets Files Forms Issues Photos

Supporting information

Kendall County New Office Project. CCCS Project Number 221071.



1. Work Log

	Crew	# Workers	# Total hours	Work performed
	BP #2 General Trades - Lite Construction	5	40	crew worked on roof deck barrier, fascia at north and east side of site
	BP #6 Masonry - Jimmy'z Masonry	1	8	worked on vapor barrier at exterior of site
	BP #13 Electrical - CSN Electric	2	16	crew worked on electrical piping on first floor and basement clean up today
	BP #7 Roofing - Filotto Roofing	4	32	crew worked on roof shingles today
Totals		12	96	

References

Photos (12)



IMG_1043 **Taken on** Jan 31, 2024, 12:49 PM CST **Added on** Jan 31, 2024, 1:20 PM CST **Added by** Ken Gleason



IMG_1050 **Taken on** Jan 31, 2024, 12:56 PM CST **Added on** Jan 31, 2024, 1:21 PM CST **Added by** Ken Gleason



IMG_1051 **Taken on** Jan 31, 2024, 1:01 PM CST **Added on** Jan 31, 2024, 1:21 PM CST **Added by** Ken Gleason



IMG_1046 **Taken on** Jan 31, 2024, 12:55 PM CST **Added on** Jan 31, 2024, 1:20 PM CST **Added by** Ken Gleason

Form detail report

22-1071 (BUILD) Kendall County PH1 Clerk Building



IMG_1049 **Taken on** Jan 31, 2024, 12:56 PM CST **Added on** Jan 31, 2024, 1:21 PM CST **Added by** Ken Gleason



IMG_1054 **Taken on** Jan 31, 2024, 1:04 PM CST **Added on** Jan 31, 2024, 1:21 PM CST **Added by** Ken Gleason



IMG_1044 **Taken on** Jan 31, 2024, 12:51 PM CST **Added on** Jan 31, 2024, 1:20 PM CST **Added by** Ken Gleason



IMG_1053 **Taken on** Jan 31, 2024, 1:04 PM CST **Added on** Jan 31, 2024, 1:21 PM CST **Added by** Ken Gleason

Form detail report

22-1071 (BUILD) Kendall County PH1 Clerk Building



IMG_1052 **Taken on** Jan 31, 2024, 1:02 PM CST **Added on** Jan 31, 2024, 1:21 PM CST **Added by** Ken Gleason



IMG_1045 **Taken on** Jan 31, 2024, 12:55 PM CST **Added on** Jan 31, 2024, 1:20 PM CST **Added by** Ken Gleason



IMG_1047 **Taken on** Jan 31, 2024, 12:55 PM CST **Added on** Jan 31, 2024, 1:20 PM CST **Added by** Ken Gleason



IMG_1048 **Taken on** Jan 31, 2024, 12:55 PM CST **Added on** Jan 31, 2024, 1:20 PM CST **Added by** Ken Gleason



SECTION 5: ARCHITECTURAL & ENGINEERING FIELD REPORTS

FIELD OBSERVATION CONFIRMATION

Date:	2024-01-	02	Observation Time:	3:52 PM
Re: Client: Project:	Kendall C	L COUNTY PHASE 1 CLERK BLDG County 	Weather Conditions:	36F Partly Cloudy
Prepare		Lauren Kiley Cordogan Clark & Associates	Phone: Fax:	630.896.4678 630.896.4987
Field Re	port Numb	per: 240102		
Est % Co	ompletion	32%	Conformance With Schedu	l e (+/-) : 0 days
Work In	Progress:	Roof sheathing and underlayment, fi lighting.	re protection piping, electrical d	listribution and

Observations:

- 1. Roof deck plywood sheathing and synthetic underlayment appears to be near completion.
- 2. Wood blocking for fascia is being installed along the perimeter of the roof framing edge.
- 3. Interior hollow metal frames and window installation is in progress.
- 4. Fire protection piping is in progress, at the basement level piping is being run throughout Voter
- Staging/ Storage 001. At first floor level piping is run above arch in Vestibule 100 for non-freeze system.
- 5. Mechanical equipment has been placed on rails at the equipment pad area.
- 6. Metal bollards have been located and post installed in the concrete equipment pad.
- 7. Site lighting concrete bases and new fire hydrant have been installed on the west.

Items to Verify:

1. The bottom of the precast plank in the basement has condensation and causing puddling on the floor. As discussed with CM, heaters will be provided in next couple weeks, verify this will help eliminate the condensation.

2. Due to the condensation in the basement, verify lighting currently installed will not be damaged.

Information Or Action Required:

1. Seal and tape seams between exterior wall sheathing per manufacturer instructions and specification 061600, in preparation for AVM barrier application.

2. Coordinate vertical sprinkler lines in Basement with electrical panels and adjacent owner equipment.

PHOTOGRAPHIC DOCUMENTATION

Date: 2024-01-02

Observation Time: 3:52 PM

Re: KENDALL COUNTY PHASE 1 CLERK BLDG Project: 221071 Weather Conditions: 36F Partly Cloudy



Gaps in Exterior Sheathing



Roof Sheathing and Underlayment Progress on South



Equipment Pad and Progress on East



Mechanical Equipment on Rails

PHOTOGRAPHIC DOCUMENTATION

Date: 2024-01-02

Re: KENDALL COUNTY PHASE 1 CLERK BLDG Project: 221071 Observation Time: 3:52 PM

Weather Conditions: 36F Partly Cloudy



Wood Blocking Fascia



Fascia at Entry Gable



Interior HM Frames



Sprinkler System Piping



Sprinkler Progress and Condensation



Lighting Progress in Basement



Site Lighting on West



Fire Hydrant on West

FIELD OBSERVATION CONFIRMATION

Date:	2024-01-	16	Observation Time:	6:03 PM
Re: Client: Project:	Kendall C	L COUNTY PHASE 1 CLERK BLDG County 	Weather Conditions:	-8F Sunny
Prepare	•	Lauren Kiley Cordogan Clark & Associates	Phone: Fax:	630.896.4678 630.896.4987
Field Re	port Num	per: 240116		
Est % Co	ompletion	34%	Conformance With Schedu	le (+/-): 0 days
Work In	Progress:	Electrical lighting and distribution in the setup, ductwork, and interior stud wall	· · · · ·	g, equipment
•				

Observations:

1. Electrical C/T cabinet, meter, disconnect, ATS, MDP, transformer are mounted and work is in progress

2. Surface mounted lighting is in progress in Voter Staging/ Storage 001. (1) row appears to be complete

3. Unit heater UH, is installed and appears to be functioning in Staging/ Receiving 002.

4. VRF units are installed in the basement and appear to be protected with plastic covering.

5. Gas piping is in progress in the basement, piping is run through exterior wall in Mech 003B.

6. Ductwork is in progress on the first floor and is being insulated.

7. Shingles, ridge vent and chimney framing is in progress on the roof and will continue pending weather.

8. Soffits are in progress of being covered with sheathing.

Items to Verify:

1. Gas piping is run through exterior wall, verify opening in wall is sealed tight and coordinate with cast stone installation.

2. Due to recent cold temperatures, verify all temperature sensitive materials are installed per manufacturer instructions.

Information Or Action Required:

1. Piping stub up in Toilet 6 will need to be relocated to be concealed in wall. As installed, the stem will conflict with toilet and required clearances.

Additional framing will be required to conceal piping stub up in Voter Office 105. Information to follow.
 Additional framing will be required to conceal piping stub up in Staging/ Work Area 106. Information to follow.

Attachments:

Progress Photos

PHOTOGRAPHIC DOCUMENTATION

Date: 2024-01-16

Observation Time: 6:03 PM

Re: KENDALL COUNTY PHASE 1 CLERK BLDG Project: 221071 Weather Conditions: -8F Sunny



Electrical Equipment in Elec 003A



Piping Stub Up in Toilet 6



Piping Stub Up in Voter Office 105



Gas Piping Through Exterior

PHOTOGRAPHIC DOCUMENTATION

Date: 2024-01-16

Observation Time: 6:03 PM

Re: KENDALL COUNTY PHASE 1 CLERK BLDG Project: 221071 Weather Conditions: -8F Sunny



Unit Heater in Staging/Receiving





Ductwork to Exterior Louver



Roofing Progress

Soffits and East Side



Stub Up in Staging/ Work Area



Gas Piping



Overall Progress

FIELD OBSERVATION CONFIRMATION

Est % Completion: 38%		n: 38%	Conformance With Schedu	l e (+/-) : 0 days
Field Re	port Num	nber: 240130		
Prepare	d By:	Lauren Kiley Cordogan Clark & Associates	Phone: Fax:	630.896.4678 630.896.4987
Re: Client: Project:	Kendall	LL COUNTY PHASE 1 CLERK BLDG County 	Weather Conditions:	38F Overcast
Date:	2024-01	-30	Observation Time:	3:18 PM

Work In Progress: Roof shingle installation, electrical rough in on first floor, plastic sheeting for attic cap, ramp foundation wall framing and rebar placement.

Observations:

1. Roof shingle installation is near completion, and appears to be about 80% complete.

2. Preparation for concrete foundation at ramp is in progress, walls are framed for pour and epoxy coated rebar appears to be in place.

3. Plastic sheeting is being placed at the top of stud framed wall level for attic cap construction.

4. Mechanical ductwork installation is in progress for louver server Toilet 7.

5. Outgoing sanitary piping is in progress in Basement from Sprinkler Room to Voter Staging/Storage.

6. The stud framing for the roof returns appears to be in progress.

7. Electrical panel work is continuing in Elec 003A. EP-2 control panel installation is in progress in Mech.

8. Construction fencing has been relocated so owner has access to half of west lot, as requested.

Items to Verify:

1. Any penetrations through concrete wall for equipment on the east needs to be sealed tight. Verify detail where there are multiple pipes running through the concrete wall to outdoor units.

2. On east wall of Voter Registration/ Training 103, outlets for TV appear to be 42" above floor level and will be exposed, verify if this is acceptable to the owner.

3. Minimal amount of water discovered on floor near door 104A, verify if this is related to construction crew or potential roof leak.

Information Or Action Required:

1. In the basement, there is a gap between CMU and bottom of precast planks, CCA to confirm if insulation infill is required.

2. Piping/ conduit appear to be installed in gap between CMU and precast planks. The planks may deflect and cause damage to the pipe/conduit. Relocate to avoid potential damage.

3. Coordinate future rough in walk through in field with owner to confirm electrical power/ data locations. 4. In Mech 003, the occupancy sensor appears to be slightly obstructed and so you have to walk in the middle of the space to activate. Relocate occupancy sensor to opposite side of fixture so lighting activates upon entry.

Attachments:

Progress Photos

PHOTOGRAPHIC DOCUMENTATION

Date: 2024-01-30

Observation Time: 3:18 PM

Re: KENDALL COUNTY PHASE 1 CLERK BLDG Project: 221071 Weather Conditions: 38F Overcast



Ramp Foundation Preparation



Roof Shingle Progress



Pipe Penetrations for Outdoor Units



Plastic Sheeting Installation

PHOTOGRAPHIC DOCUMENTATION

Date: 2024-01-30

Observation Time: 3:18 PM

Re: KENDALL COUNTY PHASE 1 CLERK BLDG Project: 221071 Weather Conditions: 38F Overcast



Duct for Louver on East



Sanitary Piping in Sprinkler Rm



Outlet Boxes for TV



Conduit in Gap between CMU and Planks



Occupancy Sensor on Light in Mech



Roof Return Framing



Stair Landing Support Opening



Overall Progress View





960 Ridgeway Avenue Aurora, Illinois 60506 T: 630.896.4678 F: 630.896.4987

Aurora, Illinois Chicago, Illinois Davenport, Iowa Lafayette, Indiana St. Louis, Missouri Sawyer, Michigan Madrid, Spain

cordoganclark.com



Kendall County Agenda Briefing

Meeting Type:	Committee of the Whole
Meeting Date:	2/15/2024
Subject:	Phase 1 January Monthly Report and Contingency Reduction #5
Prepared by:	Dan Polvere, Facilities Director
Department:	Facilities

Action Requested:

Review of Phase 1 Contingency Reduction No. 5

Board/Committee Review:

NA

Fiscal impact:

\$22,713 Reduction of Phase 1 Contingency

Background and Discussion:

Progress continues on County Office Building #2 (107 W. Fox Street), with work on target to be completed by June 1st. Cordogan Clark's detailed report of January progress is attached.

Contingency reduction No. 5 includes costs for 1) lowering the water main to accommodate other equipment for the connection of the water main to the sprinkler system and 2) electrical changes do to coordination issues and final furniture & elevator designs.

The total request for Contingency Reduction No. 5 is \$22,713, with revised contract amounts as follows:

•	Omega Plumbing:	\$144,702	(2,202 increase)
•	CSN Electric:	\$998,633	(\$8,852, \$9,808 & \$1,851 increases)

The current available contingency is \$209,792.

Staff Recommendation:

Approve Motion to forward Contingency Reduction No. 5 to County Board

Attachments:

- Cordogan Clark January monthly report
- Contingency Reduction No. 5 dated 2-7-2024
- Phase 1 Drone Pic East Side 2 8 24
- Phase 1 Drone Pic Northwest Side 2 8 24

CONTINGENCY REDUCTION

Owner:

Architect: 🗌 struction Manager:

Construction Manager:
Contractor:

Field:

PROJECT: Phase One New Office Building	CONTINGENCY RE	DUCTION #: CR-005
CLIENT: Kendall County 111 W. Fox Street	DATE: CONTRACT DATE:	2/7/2024
Yorkville, IL 60560	PROJECT #:	221071
CONSTRUCTION		
MANAGER: Cordogan Clark Consulting Services		
960 Ridgeway Avenue		

Aurora, IL 60506

The Contract is changed as follows:

 Omega Plumbing PR-007 Lower water main to accommodate other equipment for the connection to water main in the sprinkler 	\$2,202.00
New Contract Amount: \$144,702.00	
 CSN Electric PR-004 Electrical Changes & ASI-012 Credit for coordination of submitted items, products, and equipment. 	\$8,852.00
PR-005 Wiremold and Floor Boxes required by Voter layout changes.	\$9,808.00
ASI-009 Elevator Electrical Changes required by Electrical Contractor. New Contract Amount: \$998,633.00	\$1,851.00

SUB-TOTAL FOR CONTINGENCY REDUCTION:	\$22,713.00
The Original Contingency was:	\$505,200.00
Net Change by previously authorized Contingency Reductions:	\$272,695.00
The Contingency prior to this reduction was:	\$232,505.00
The Contingency will be decreased by this reduction in the amount of:	\$22,713.00
The new Contingency with this reduction will be:	\$209,792.00
The Contract Time will be increased by:	(0)days
The date of Substantial Completion as of the date of this Contingency Reduction, therefore is:	unchanged.

NOTE: This Contingency Reduction does not include changes in the Contract Sum, Contract Time or Guarnteed Maximum Price that have been authorized by Construction Change Directive until cost and time have been agreed by both the Owner, Contractor & Construction Manager, in which case a Change Order is executed to superscede the Construction Change Directive

NOT VALID UNTIL SIGNED BY THE CONSTRUCTION MANAGER & OWNER.

CONSTRUCTION MANAGER:	OWNER:
Cordogan Clark Consulting Services, Inc. 960 Ridgeway Avenue Aurora, IL 60505	Kendall County 111 W. Fox Street Yorkville, IL 60560
Ву:	Ву:
Date:	Date:



Kendall County Agenda Briefing

Meeting Type:	Committee of the Whole
Meeting Date:	2/15/2024
Subject:	Phase 1 Office, Lobby and Training Furniture Procurement
Prepared by:	Dan G. Polvere
Department:	Facilities Management

Action Requested:

Review/Approve Phase 1 Office, Lobby and Training Furniture procurement via the TIPS government Co-Op Contract Number 210305 at a cost not-to-exceed \$310,648.

Board/Committee Review:

Motion to Forward to County Board

Fiscal impact:

\$310,648 Reduction of the remaining Phase 1 \$315,648 Furniture, Fixtures & Equipment (FF&E) Budget

Background and Discussion:

Per the Phase 1 interior design (see attached), procurement of Lacasse and RightAngle furniture for the offices, lobby and training areas via the TIPS government Co-Op.

The Phase 1 Furniture, Fixtures and Equipment budget is \$376,473 (-\$60,825 for Bradford Storage Solutions) = \$315,648 remaining budget.

Staff Recommendation:

Approve Motion to forward Office, Lobby and Training furniture to County Board

Attachments:

- Office, Lobby and Training Furniture Plans
- Lacasse Quote
- RightAngle Quote




PH1 CLERK BUILDING

FURNITURE PLANS

JANUARY 30, 2024








FIRST FLOOR - OVERALL FURNITURE PLAN

KENDALL COUNTY

ALTERNATE FURNITURE PLAN TRAINING 103













Lacasse Sonoma Lounge Chair Pouf Ottoman 24"Dia with laminate top Upholstered



Loveseat Upholstered



Lacasse Cube200



FIRST FLOOR - FURNITURE PLAN

KENDALL COUNTY

PH1 CLERK BUILDING

Lacasse 400E - Height Adjustable Desks 36x84W Desk B/F 36x72W Desk B/F (Office 105) 24x48W Return (with power module) 24Dx84W Credenza Lateral File 24Dx84W Credenza Lateral File (105) Pencil Drawer Wall-Mount Tackboard 72Wx21H

Wall-Mount Hutch 16Dx72Wx22H

4H Lateral File 36Wx20Dx58H

Lacasse Paradigm Cubicles Metal Mobile BBF with Multi-unit Pedestal Lateral each 42H Panels/29H Panels (hardwired) 104: Adj Height Table 29x64", 24Dx84W 118: Adj Height Table 29x64", 24Dx84W 123: Adj Height Table 29x64", 20Dx84W



Height Adjustable Tables (plug-in) (104, 118, 123 cubicles)

Lacasse Sonoma



Lacasse Brylee 2.0 Guest Chair Uphol Seat & Back Arms No Arms (108 only) Casters



Lacasse Upswing Task Chair Mesh Back Uphol Seat, Arms



Lacasse **Rackup Stool** Armless Uphol Seat

JANUARY 30, 2024

PAGE 3

Square Table 24Wx24Dx17H

Quorum Table Angled Legs 108: 48x60" 120: 36x36" 125: 42x72" w/ power



KENDALL COUNTY



RightAngle Romeo Flip Nesting Table 18Dx48W (single person), casters, 12 Qty 18Dx54W (double person), casters, 10 Qty with power module black 1 AC Outlet

- 1 USB Type A
- 1 USB Type C



Lacasse Rackup Nesting Chairs Arms, Mesh Backrest Uphol seat Casters 30 Qty

JANUARY 30, 2024

PAGE 4



KENDALL C.C. BLDG

Project number :	GL-50066
Quotation number: 50066	TIPS Contract # 210305
02-01-2024	REV11
EXP 02-29-2024	

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$	
101-L	OBBY						
1	CU2B1M-E8	CUBE 200 - Single-section Base (Legs)	ARO	6	228.00 \$	1,368.00 \$	ì
2	CU2-TF	CUBE 200 - Legless Unit without Access	ARO	6	334.80 \$	2,008.80 \$	i
3	SO2-E8-GR1	SONOMA - Upholstered Lounge Loveseat w/ Metal Legs	ARO	2	1,814.40 \$	3,628.80 \$	i
4	SO1-E8-GR1	SONOMA - Upholstered Lounge Armchair w/ Metal Legs	ARO	12	1,455.60 \$	17,467.20 \$	i
5	RK52-E3-M??-GR1-ST-P -NB-HDW	Stool, no arms, mesh backrest	UNN	1	646.20 \$	646.20 \$,
					<u>25,119.00</u> \$		
103- 1	RAINNING						
6	RK03-E3-M??-GR1-HDW -FA-DP	Nesting chairs, with arms, mesh backrest, 2-pack	UNC	15	792.60 \$	11,889.00 \$	Ì
					<u>11,889.00\$</u>		

104- V	OTER OPERATION	IS					
7	LGC-DR20P	Storage drawer	LU	A 6	131.40	\$ 788.40	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$	
8	UP13-E3-M??-GR1-SYN- P-AB-HDW-HA8	Task chair, with arms, mesh backrest	UNC	6	499.20 \$	2,995.20	\$
9	RID??-183028CO	Metal multi unit, file drawer on right, 30"W, 18"D, 27 7/8"H,	SSF	6	1,233.00 \$	7,398.00	\$
10	RID??-183641LF3	Metal lateral file, 3-high, 36"W, 18"D, 40 1/16"H,	SSF	6	1,020.60 \$	6,123.60	\$
11	КМРМ-1519-3	Mobile pedestal w/ metal fr., B/B/F, 18 7/8D	PAU	6	532.80 \$	3,196.80	\$
12	KUR-2484-1-G	Std. rect. surf., TFL, grommet, 24Dx84W	PAU	6	342.00 \$	2,052.00	\$
13	KER3-C1-?	3-circ., duplex receptacles, circuit #1, pack of 10	PAU	1	201.00 \$	201.00	\$
14	KER3-C2-?	3-circ., duplex receptacles, circuit #2, pack of 10	PAU	1	201.00 \$	201.00	\$
15	KVWS-30	Wall starter, 29 7/8H	PAU	2	67.20 \$	134.40	\$
16	КРМА-3042-3Р	Acoust. panel, pwr. 3-circ., 29 7/8Hx42W	PAU	12	529.80 \$	6,357.60	\$
17	KVET-42	End-of-run trims, full height, 42 1/4H	PAU	7	116.40 \$	814.80	\$
18	KVPLA-42-30	L junction kit, variable height, 42 1/4H lowering to 29 7/8H	PAU	2	138.00 \$	276.00	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$
19	КVРТА-42-30	T junction kit, var. height type A, 42 1/4H lowering to 29 7/8H	PAU	4	87.60 \$	350.40 \$
20	KPMA-4242-NN	Acoust. panel, non-pwr., 42 1/4Hx42W	PAU	6	462.60 \$	2,775.60 \$
21	KPMA-4248-NN	Acoust. panel, non-pwr., 42 1/4Hx48W	PAU	6	508.20 \$	3,049.20 \$
22	KACB-P-2	Standard cantilever brackets, pair	PAU	3	81.60 \$	244.80 \$
23	КАРВ-2	Panel brackets, pair	PAU	9	31.80 \$	286.20 \$
24	KEB3-S-6	3-circ., hardwire base feed	PAU	2	162.00 \$	324.00 \$
25	KEJ3-G	3-circ., jumpers for electrified junction, type G	PAU	4	61.20 \$	244.80 \$
26	T1NN?-RCA2964GC	RECT HEIGHT ADJ TABLE - 1" thermofused lam w/smooth edge, matching edge color, 29x64"	QMU	6	1,491.60 \$	8,949.60 \$

					<u>46,76</u>	<u>3.40\$</u>		
105- C	LOSED OFFICE							
27	BL32C-E3-GR1-APW	Guest/stack chairs, with arms, on casters	UNN	2	373.80	\$	747.60	\$
28	LGC-PCV1USB2P	FLUSH MOUNT ROUND ELECTRICAL COMUNICATION MODULE- INCLUDE 2 ELECTRICAL OUTLETS AND 2 USB PORT- INSTALLED ON THE RETURN		1	355.80	\$	355.80	\$

Line	Product number	Description	Cat SC	Qty	Cost\$	Ext. Cost \$	
29	UP13-E3-M??-GR1-SYN- P-AB-HDW-HA8	Task chair, with arms, mesh backrest	UNN	1	499.20 \$	499.20	\$
30	4N?N-1830LFL	Lateral File,Modular,F/F,Lock,I 18"(448MM)D x 30"(748MM)W	LU4	1	703.20 \$	703.20	\$
31	7?NN-DT2448C.1	Work Surface,Rect,Tx. 2 Edg,9" mod panel. Pnl,2 Recessed Legs,1 Grommet 24"(600MM)Dx48"(1200MM)W	LU7	1	556.80 \$	556.80	\$
32	7?NN-DT2472A	Work Surface,Rect,Tx. 2 Edg,Full-Ht Mod. Pnl,2 Full-Width Legs,1 Grommet 24"(600MM)Dx72"(1800MM)W	LU7	1	672.60 \$	672.60	\$
33	41NN-EM722216P	Hutch,Wall-Mounted w/Doors,4 Doors 16"(400MM)D x 72"(1800MM)W x 22"(553MM)H	LU4	1	935.40 \$	935.40	\$
34	LGC-DR20P	Storage drawer	LUA	1	131.40 \$	131.40	\$
35	LGC-LED44	LED Task Lights, 44"	LUA	1	585.60 \$	585.60	\$
36	LGC-TK7221M	Wall-Mount Tackboards, 72 x ½ x 21	LUA	1	324.60 \$	324.60	\$
37	LN??-203658LF4	LATERAL FILE / 4 STEEL DRAWERS, 36x20x58	LMS	1	1,758.00 \$	1,758.00	\$
38	N1NDN-F201621	Low Stor. Mod., w/ B/F, 16 x 20 x 21	UNX	1	934.80 \$	934.80	\$
39	N5NLN-RT3672FGK	Height adj. desk w/ file drawer, 1-1/2" thick, 72 x 36 x 26-43.5	UNX	1	3,424.80 \$	3,424.80	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$
40	NNNNN-CU1518	Cushion, 18 x 15 x 0.875	UNX	1	226.20 \$	226.20 \$

<u>11,856.00\$</u>

106							
41	BL32C-E3-GR1-APW	Guest/stack chairs, with arms, on casters	UNN	2	373.80 \$	747.60	\$
42	RID??-183641LF3	Metal lateral file, 3-high, 36"W, 18"D, 40 1/16"H,	SSF	8	1,020.60 \$	8,164.80	\$
43	RK52-E3-M??-GR1-ST-P -NB-HDW	Stool, no arms, mesh backrest, GRADE 1	UNN	2	646.20 \$	1,292.40	\$

					<u>10,204.80\$</u>		
108- E	BREAK ROOM						
44	BL32C-E3-GR1-APW	Guest/stack chairs, with arms, on casters	UNN	12	373.80 \$	4,485.60	\$
45	ST5NNN-RC4860	RECTANGULAR TOP - 1-1/2" thermofused lam w/smooth edge, matching edge color, 48X60	QMU	2	617.40 \$	1,234.80	\$
46	TNNN?-ATL228	METAL ANGLED LEG 29H, PAIR	QMU	4	289.20 \$	1,156.80	\$

 6,877.20\$

 114-LACTATION ROOM

 47
 HRT24-E8-GR1
 ROUD TABLE
 ARO
 1
 351.60
 \$

Space planner agent :	Annie-Pier Noel
opaco plainioi agonti	

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$
48	SO1-E8-GR1	SONOMA - Upholstered Lounge Armchair w/ Metal Legs	ARO	1	1,455.60 \$	1,455.60 \$

<u>1.807.20\$</u>

118- C	LERK DEPARTMENT						
49	BL32C-E3-GR1-APW	Guest/stack chairs, with arms, on casters	UNN	6	373.80 \$	2,242.80	\$
50	RID??-183654LF4	Metal lateral file, 4-high, 36"W, 18"D, 53 3/8"H,	SSF	8	1,282.20 \$	10,257.60	\$
51	S41NN-TDM3660	RECESSED FULL MODESTY PANEL, 36 X 60	*	2	600.60 \$	1,201.20	\$
52	UP13-E3-M??-GR1-SYN- P-AB-HDW-HA8	Task chair, with arms, mesh backrest	UNN	5	499.20 \$	2,496.00	\$
53	RID??-183028CO	Metal multi unit, file drawer on right, 30"W, 18"D, 27 7/8"H,	SSF	2	1,233.00 \$	2,466.00	\$
54	RID??-183641LF3	Metal lateral file, 3-high, 36"W, 18"D, 40 1/16"H,	SSF	5	1,020.60 \$	5,103.00	\$
55	KMCU-1519	Pedestal cushion, 18 7/8D	PAU	4	219.00 \$	876.00	\$
56	КМРМ-1519-3	Mobile pedestal w/ metal fr., B/B/F, 18 7/8D	PAU	4	532.80 \$	2,131.20	\$
57	KUR-2484-1-G	Std. rect. surf., TFL, grommet, 24Dx84W	PAU	4	342.00 \$	1,368.00	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$	
58	KER3-C1-?	3-circ., duplex receptacles, circuit #1, pack of 10	PAU	1	201.00 \$	201.00	\$
59	KER3-C2-?	3-circ., duplex receptacles, circuit #2, pack of 10	PAU	1	201.00 \$	201.00	\$
60	KVET-42	End-of-run trims, full height, 42 1/4H	PAU	5	116.40 \$	582.00	\$
61	KVPT-42	T junction kit, full height, 42 1/4H	PAU	1	84.00 \$	84.00	\$
62	КРМА-4242-3Р	Acoust. panel, pwr. 3-circ., 42 1/4Hx42W	PAU	4	567.60 \$	2,270.40	\$
63	KPMA-4242-NN	Acoust. panel, non-pwr., 42 1/4Hx42W	PAU	4	462.60 \$	1,850.40	\$
64	KPMA-4248-NN	Acoust. panel, non-pwr., 42 1/4Hx48W	PAU	4	508.20 \$	2,032.80	\$
65	RID??-CO183028	Metal multi unit, file drawer on left, 30"W, 18"D, 27 7/8"H,	SSF	2	1,233.00\$	2,466.00	\$
66	KACB-P-2	Standard cantilever brackets, pair	PAU	2	81.60 \$	163.20	\$
67	КАРВ-2	Panel brackets, pair	PAU	6	31.80 \$	190.80	\$
68	KEB3-S-6	3-circ., hardwire base feed	PAU	1	162.00 \$	162.00	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$
69	KEJ3-G	3-circ., jumpers for electrified junction, type G	PAU	1	61.20 \$	61.20 \$
70	LGC-DR20P	Storage drawer	LUA	4	131.40 \$	525.60 \$
71	LU-SCL2436	LAMINATE STACK SCREEN SINGLE PACK, 24"H	GIU	2	168.00 \$	336.00 \$
72	LU-SCL14236S	FREESTANDING SCREEN W/ SILVER BASE, 42"H	GIU	2	337.20 \$	674.40 \$
73	4N?N-P1518UFL	Pedestal,Modular,B/B/F,Pencil Tray,w/Lock, 18"(448MM)D x 15"(388MM)W x 28"(711MM)H	LU4	2	607.80 \$	1,215.60 \$
74	T1NN?-RCA2964GC	RECT HEIGHT ADJ TABLE - 1" thermofused lam w/smooth edge, matching edge color, 29x64"	QMU	4	1,491.60 \$	5,966.40 \$
75	R1NNN-TO3618	Thermofused laminate top for 18"D metal storage unit, 36"W, 18"D, 1"H	SSN	3	209.40 \$	628.20 \$
76	R1NNN-TO7218	Thermofused laminate top for 18"D metal storage units, 72"W, 18"D, 1"H	SSN	5	267.60 \$	1,338.00 \$

			<u>49,090.80\$</u>					
120-12	1-122- CLOSED OF	FICE						
77	BL32C-E3-GR1-APW	Guest/stack chairs, with arms, on casters	UNN	6	373.80	\$	2,242.80	\$
78	LGC-PCV1USB2P	FLUSH MOUNT ROUND ELECTRICAL COMUNICATION MODULE- INCLUDE 2 ELECTRICAL OUTLETS AND 2 USB PORT- INSTALLED ON THE RETURN		3	355.80	\$	1,067.40	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$	
79	T1NN?-SQR3629DC	SQUARE TABLE BASE DISC, - 1" thermofused lam w/smooth edge, matching edge color, black accent, 36"D	QMU	1	784.80 \$	784.80	\$
80	UP13-E3-M??-GR1-SYN- P-AB-HDW-HA8	Task chair, with arms, mesh backrest	UNN	3	499.20 \$	1,497.60	\$
81	4N?N-1830LFL	Lateral File,Modular,F/F,Lock,18"(448MM)D x 30"(748MM)W	LU4	3	703.20 \$	2,109.60	\$
82	7?NN-DT2448C.1	Work Surface,Rect,Tx. 2 Edg,9" mod panel. Pnl,2 Recessed Legs,1 Grommet 24"(600MM)Dx48"(1200MM)W	LU7	3	556.80 \$	1,670.40	\$
83	S7?NN-DT2484A	Work Surface,Rect,Tx. 2 Edg,Full-Ht Mod. Pnl,2 Full-Width Legs,1 Grommet 24"(600MM)Dx84"W, half gable in the middle	LU7	3	882.00 \$	2,646.00	\$
84	41NN-EM722216P	Hutch,Wall-Mounted w/Doors,4 Doors 16"(400MM)D x 72"(1800MM)W x 22"(553MM)H	LU4	3	935.40 \$	2,806.20	\$
85	LGC-DR20P	Storage drawer	LUA	3	131.40 \$	394.20	\$
86	LGC-LED44	LED Task Lights, 44"	LUA	3	585.60 \$	1,756.80	\$
87	LGC-TK7221M	Wall-Mount Tackboards, 72 x ½ x 21	LUA	3	324.60 \$	973.80	\$
88	LN??-203658LF4	LATERAL FILE / 4 STEEL DRAWERS,36x20x58	LMS	3	1,758.00 \$	5,274.00	\$
89	N1NDN-F201621	Low Stor. Mod., w/ B/F, 16 x 20 x 21	UNX	3	934.80 \$	2,804.40	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$
90	N5NLN-RT3684FG?	Height adj. desk w/ file drawer, 1-1/2" thick, 84 x 36 x 26-43.5	UNX	1	3,469.80 \$	3,469.80 \$
91	N5NRN-RT3684FG?	Height adj. desk w/ file drawer, 1-1/2" thick, 84 x 36 x 26-43.5	UNX	2	3,469.80 \$	6,939.60 \$
92	NNNNN-CU1518	Cushion, 18 x 15 x 0.875	UNX	3	226.20 \$	678.60 \$

<u>37,116.00\$</u>

123- R	ECORDER DEPARTE	EMENT					
93	UP13-E3-M??-GR1-SYN- P-AB-HDW-HA8	Task chair, with arms, mesh backrest	UNN	1	499.20 \$	499.20	\$
94	UP13-E3-M??-GR1-SYN- P-AB-HDW-HA8	Task chair, with arms, mesh backrest	UNN	4	499.20 \$	1,996.80	\$
95	RID??-183028CO	Metal multi unit, file drawer on right, 30"W, 18"D, 27 7/8"H,	SSF	4	1,233.00 \$	4,932.00	\$
96	RID??-183654LF4	Metal lateral file, 4-high, 36"W, 18"D, 53 3/8"H,	SSF	2	1,282.20 \$	2,564.40	\$
97	KMCU-1519	Pedestal cushion, 18 7/8D	PAU	4	219.00 \$	876.00	\$
98	КМРМ-1519-3	Mobile pedestal w/ metal fr., B/B/F, 18 7/8D	PAU	4	532.80 \$	2,131.20	\$
99	KUR-2084-1-G	Std. rect. surf., TFL, grommet, 20Dx84W	PAU	4	300.00 \$	1,200.00	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$
100	KER3-C1-?	3-circ., duplex receptacles, circuit #1, pack of 10	PAU	1	201.00 \$	201.00 \$
101	KER3-C2-?	3-circ., duplex receptacles, circuit #2, pack of 10	PAU	1	201.00 \$	201.00 \$
102	KVWS-30	Wall starter, 29 7/8H	PAU	2	67.20 \$	134.40 \$
103	КРМА-3042-3Р	Acoust. panel, pwr. 3-circ., 29 7/8Hx42W	PAU	8	529.80 \$	4,238.40 \$
104	KVET-42	End-of-run trims, full height, 42 1/4H	PAU	4	116.40 \$	465.60 \$
105	KVPL-42	L junction kit, full height, 42 1/4H	PAU	2	138.00 \$	276.00 \$
106	КVРТА-42-30	T junction kit, var. height type A, 42 1/4H lowering to 29 7/8H	PAU	2	87.60 \$	175.20 \$
107	KPMA-4236-NN	Pan. acoust. tissu, non él., 42 1/4Hx36L	PAF	4	444.60 \$	1,778.40 \$
108	KPMA-4248-NN	Acoust. panel, non-pwr., 42 1/4Hx48W	PAU	4	508.20 \$	2,032.80 \$
109	KACB-P-2	Standard cantilever brackets, pair	PAU	2	81.60 \$	163.20 \$
110	KAPB-2	Panel brackets, pair	PAU	6	31.80 \$	190.80 \$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$
111	KEB3-S-6	3-circ., hardwire base feed	PAU	2	162.00 \$	324.00 \$
112	KEJ3-G	3-circ., jumpers for electrified junction, type G	PAU	2	61.20 \$	122.40 \$
113	LGC-DR20P	Storage drawer	LUA	4	131.40 \$	525.60 \$
114	T1NN?-RCA2964GC	RECT HEIGHT ADJ TABLE - 1" thermofused lam w/smooth edge, matching edge color, 29x64"	QMU	4	1,491.60\$	5,966.40 \$
115	R1NNN-TO7218	Thermofused laminate top for 18"D metal storage units, 72"W, 18"D, 1"H	SSN	1	267.60 \$	267.60 \$

<u>31,262.40\$</u>

124- RE							
116	BL32C-E3-GR1-APW	Guest/stack chairs, with arms, on casters	UNN*	2	373.80	\$ 747.60	\$
117	LGC-PCV1USB2P	FLUSH MOUNT ROUND ELECTRICAL COMUNICATION MODULE- INCLUDE 2 ELECTRICAL OUTLETS AND 2 USB PORT- INSTALLED ON THE RETURN		1	355.80	\$ 355.80	\$
118	N5NLN-RT3684FGK	Height adj. desk w/ file drawer, 1-1/2" thick, 84 x 36 x 26-43.5	UNX	1	3,469.80	\$ 3,469.80) \$
119	NNNN-CU1518	Cushion, 18 x 15 x 0.875	UNX	1	226.20	\$ 226.20	\$
120	UP13-E3-M??-GR1-SYN- P-AB-HDW-HA8	Task chair, with arms, mesh backrest	UNN	1	499.20	\$ 499.20	\$

Line	Product number	Description	Cat SC	Qty	Cost \$	Ext. Cost \$	
121	4N?N-1830LFL	Lateral File,Modular,F/F,Lock,18"(448MM)D x 30"(748MM)W	LU4	1	703.20 \$	703.20	\$
122	7?NN-DT2448C.1	Work Surface,Rect,Tx. 2 Edg,9" mod panel. Pnl,2 Recessed Legs,1 Grommet 24"(600MM)Dx48"(1200MM)W	LU7	1	556.80 \$	556.80	\$
123	S7?NN-DT2484A	Work Surface,Rect,Tx. 2 Edg,Full-Ht Mod. Pnl,2 Full-Width Legs,1 Grommet 24"(600MM)Dx84"W, half gable in the middle	LU4	1	882.00 \$	882.00	\$
124	41NN-EM722216P	Hutch,Wall-Mounted w/Doors,4 Doors 16"(400MM)D x 72"(1800MM)W x 22"(553MM)H	LU4	1	935.40 \$	935.40	\$
125	LGC-DR20P	Storage drawer	LUA	1	131.40 \$	131.40	\$
126	LGC-LED44	LED Task Lights, 44"	LUA	1	585.60 \$	585.60	\$
127	LGC-TK7221M	Wall-Mount Tackboards, 72 x $\frac{1}{2}$ x 21	LUA	1	324.60 \$	324.60	\$
128	N1NDN-F201621	Low Stor. Mod., w/ B/F, 16 x 20 x 21	UNX	1	934.80 \$	934.80	\$

<u>10,352.40\$</u>

125- PUBLIC WORK SPACE								
129	BL32C-E3-GR1-APW	Guest/stack chairs, with arms, on casters	UNN	8	373.80 \$	2,990.40	\$	
130	T5NN?-RC4272PC	RECTANGULAR TOP - 1-1/2" thermofused lam w/smooth edge, matching edge color, w/elec comm mod,42X72	QMU	1	1,137.60 \$	1,137.60	\$	

Line	Product number	number Description Ca		Qty	Cost \$		Ext. Cost \$	
131	TNNN?-ATL228WM	METAL ANGLED LEG 29H, WITH CABLE MGMT, PAIR,	QMU	1	308.40	\$	308.40	\$
132	TNNN?-ATL228	METAL ANGLED LEG 29H, PAIR,	QMU	1	289.20	\$	289.20	\$
					<u>4,</u> 725.	<u>60\$</u>		
Y- add	litional chair							
A- aut								
133	BL32C-E3-GR1-APW	Guest/stack chairs, with arms, on casters		8	373.80	\$	2,990.40	\$
					<u>2,990</u> .	<u>.40\$</u>		
		Subtotal			250,05	54.20	<u>\$</u>	
		Freight, Delivery and Installation		-	<u>41,707</u>	<u>7.70</u>	<u>\$</u>	
		Grand total:		<u>291,7</u>	<u>′61.90</u>		<u>\$</u>	

PLEASE NOTE:

- Specification prices are valid with our current price list at time of purchase. -
- It is the responsibility of the dealer to ensure the accuracy of this specification. -
- Any errors, discrepancies or changes must be reported immediately prior to placing an order. -
- All pieces are built using the metric system; you must specify if you need exact imperial dimensions. -
- All products are always specified with grade 1 fabric unless otherwise noted. _
- All chairs are always specified with basic options unless otherwise noted.
- No finishes, fabrics or handles are specified. -
- Drawings are for reference only. -
- This is a specification not a purchase order. -

THANK YOU FOR YOUR BUSINESS!

rightangle

K&A Manufacturing Inc.

6703 Zinser Street Schofield, WI 54476 Phone: 715-355-0222 or 800-298-4351 Fax: 866-882-9475

Fed ID: 391659382

Customer Attn: address: TIPS-Quote



Quote No. 21515

Monday, January 29, 2024

Page 1 of 2

address: **TIPS-Ouote** Phone: Reseller: SHERIDAN Ship Via: _Best Way Quote Reference: Kendall County Clerk Bldg - Flip Tables Pricing on quote is "END USER" pricing. TIPS Contract #:230301 TIPS Vendor Name: RightAngle Member: Kendall County WS9G185418GMB Part ID: Rev: Line: 1 Worksurface Type9 1-1/8" Rectangle 18"x54"x18" TFM Gray Matrix Black Edgeband Discountea Estimated List Quantity U/M Unit Price Disc % Unit Price Addl Charge Lead Time* Total Price <u>Discount</u> 10EA \$291.00000 50.00 \$145.50000 \$145.50000 \$0.00 4 Weeks \$1,455.00 Line: 2 Part ID: RFLBC184818B Rev: 2 Romeo Flip 18x48x18 Blk w/Casters Tag: (10) for 54" tops, (12) for 48" tops List <u>Discountea</u> **Estimated** Quantity U/M Addl Charge Lead Time* Total Price Unit Price Disc % Unit Price Discount 22EA \$768.00000 50.00 \$384.00000 \$384.00000 \$0.00 4 Weeks \$8,448.00 3 Part ID: 54211 Line: Rev: 1 Charging Dock, (2) USB Ports Rated at 2.25A Each (10.5 Watts) & (2) AC Receptacles w/ 10' Power Cord, Flush Table Mount. Rated at 125V 60Hz 15A, Black, Part #TVO23100-153-M-4.5AC-TR-BKR-D12 List Discountea Estimated <u>Quantity</u> <u>U/M</u> Disc % Addl Charge Unit Price Discount Unit Price Lead Time* Total Price 10EA \$116,50000 \$233.00000 50.00 \$116.50000 \$0.00 4 Weeks \$1,165.00 4 Part ID: CHARGING DOCK RECEPTACLE HOLE Line: Rev: Charging Dock Receptacle Hole for NH and R-Style List Estimated Discountea Disc % Quantity U/M Unit Price <u>Discount</u> Unit Price Addl Charge Lead Time* Total Price 10EA \$0.00000 0.00 \$0.00000 \$0.00000 \$0.00 4 Weeks \$0.00 WS9G184818GMB Part ID: Line: 5 Rev: Worksurface Type9 1-1/8" Rectangle 18"x48"x18" TFM Gray Matrix w/Black Edgebanding Estimated List Discountea Quantity U/M Unit Price Addl Charge Lead Time* Total Price Unit Price Disc % Discount 12EA \$221.00000 \$110.50000 \$110.50000 4 Weeks \$1,326.00 50.00 \$0.00 6 54816B Line: Part ID: Rev: 3" Grommet Power/USB Charging Dock w/10' Cord, (1) Grounded AC Outlets (125V 15A), (1) USB Type-A & (1) USB Type-C, Black List Discountea Estimated Unit Price Addl Charge Lead Time* Total Price Quantity U/M Disc % <u>Discount</u> Unit Price

12EA

\$281.00000

50.00

\$140.50000

\$140.50000

\$0.00

Shipping

\$1,686.00

4 Weeks

a rightangle⁻

K&A Manufacturing Inc.

6703 Zinser Street Schofield, WI 54476 Phone: 715-355-0222 or 800-298-4351 Fax: 866-882-9475

Fed ID: 391659382



Quote No. 21515

Monday, January 29, 2024

Page 2 of 2

Line:	7	Part ID:	ID: GROMMET HOLE 3 INCH				Rev:			
			3" Grommet Hole	2						
				List			<u>Discountea</u>		<u>Estimated</u>	
			<u>Quantity</u> <u>U/M</u>	<u>Unit Price</u>	<u>Disc %</u>	<u>Discount</u>	<u>Unit Price</u>	<u>Addl Charge</u>	<u>Lead Time*</u>	<u>Total Price</u>
			12EA	\$20.00000	50.00	\$10.00000	\$10.00000	\$0.00	4 Weeks	\$120.00
Line:	8	Part ID:	INSTALLATION				Rev:			
			Installation Charg	jes						
				List			<u>Discountea</u>		<u>Estimated</u>	
			<u>Quantity</u> <u>U/M</u>	<u>Unit Price</u>	Disc %	<u>Discount</u>	<u>Unit Price</u>	<u>Addl Charge</u>	Lead Time*	Total Price
			1EA	\$1450.00000	0.00	\$0.00000	\$1,450.00000	\$0.00		\$1,450.00
			List Price Total:			\$29,850.00	Discour	nted Total:		\$15,650.00
		Prices a	re Valid Until Monda	ıy, April 29, 2024						

* Please note lead time is an estimate. Appropriate lead time will be determined at time of order based on current inventory.

Unless otherwise specified above, shipping dock to dock within contiguous United States and **does not include** special services such as liftgate, limited access, inside delivery, etc.

DISCLAIMER: "This quote is based upon K&A Manufacturing / Right Angle Products understanding of the Buyer's requirements and scope of project. _ <u>It is the Buyer's responsibility</u> to ensure all product quantities, descriptions, colors, specifications and all other aspects of this estimate, are sufficient. Use of this quotation constitutes acceptance of all aspects of this estimate as well as the disclaimer."